

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001494/UQY3N2**Date:** 05/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00027252100		
Claimant Vehicle No :	SMS2611U	Insured Vehicle No :	SGX7810Z		
Date of Loss:	13/02/2022	Nature of Claim:	TP	Claim No:	SNM22D201086/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS2611U	Engine No:	A25A5253691
Make & Model:	TOYOTA CAMRY, 2.5 HYBRID ASCENT (A)	Chassis No:	JTNB23HKX03044723
Reg. Date:	19/02/2020 (Man. Year: 2019)	Odometer:	37720 km
Colour:	White		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45ZR18	Rear Tyre Size:	235/45ZR18
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,906.25	4,194.00	3,712.25	46.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	2,090.00	1,210.00	36.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,206.25	6,284.00	4,922.25	43.92
+ GST 7.00/7.00% (\$\$)	784.44	439.88	344.56	43.92
Nett Amount (\$\$)	11,990.69	6,723.88	5,266.81	43.92

INSPECTION

Date of Assignment:	16/02/2022		
Date Inspected:	21/02/2022	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2022)
Parts:	143	TOYOTA CAMRY 2.5 HYBRID ASCENT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS2611U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent/Buckled	1,143.00 FL	*1,143.00 FL
2	1		*REAR BOOT TOP LOCK	Twisted	399.00 FL	*399.00 FL
3	1		*REAR BOOT BOTTOM LOCK	Not Necessary	25.00 FL	*- FL
4	1		*REAR BOOT TOYOTA LOGO	Necessary	78.00 FL	*78.00 FL
5	1		*REAR BOOT CAMRY WORDING WITH GARNISH	Not Necessary	222.00 FL	*- FL
6	2		*REAR BOOT REFLECTOR-L/R	Serviceable	618.00 FL	*- FL
7	1		*REAR BOOT INSULATOR	Not Necessary	522.00 FL	*- FL
8	13		*REAR BOOT INSULATOR CLIP	Not Necessary	65.00 FL	*- FL
9	1		*REAR BOOT RUBBER	Twisted	194.00 FL	*194.00 FL
10	2		*REAR BOOT NUMBER PLATE LAMP-L/R	Not Necessary	356.00 FL	*- FL
11	1		*REAR BOOT HYBRID LOGO	Necessary	78.00 FL	*78.00 FL
12	1		*REAR BUMPER	Distorted	657.00 FL	*657.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
14	1		*REAR BUMPER SIDE HOLDER-L/R	Bent	138.00 FL	*138.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Dented	277.00 FL	*277.00 FL
16	1		*REAR BUMPER REFLECTORS N/S	Broken	60.00 FL	*60.00 FL
17	2		*REAR BUMPER CENTRE MOULDING,BLACK-L/R	Cracked	278.00 FL	*278.00 FL
18	1		*REAR BUMPER SENSOR (4 Pcs)	Shorted (1 Pc only)	1,568.00 FL	*392.00 FL
19	1		*REAR PANEL	Badly Dented	651.00 FL	*651.00 FL
20	1		*REAR PANEL TOP GARNISH	Twisted	296.00 FL	*296.00 FL
21	2		*TAIL LAMP ASSY-L/R	Serviceable	894.00 FL	*- FL
22	2		*TAIL LAMP LOWER RETAINER-L/R	Not Necessary	154.00 FL	*- FL
23	1		*REAR BUMPER UNDER LOWER COVER	Not Necessary	475.00 FL	*- FL
24	1		*REAR SPARE TYRE BOARD	Warped	548.00 FL	*548.00 FL
25	1		*SET REAR NUMBER PLATE WITH CASING	Serviceable	35.00 FS	*- FS
26	1		*REAR SPARE TYRE FOAM	Distorted	353.00 FL	*353.00 FL
27	1		*TAIL LAMP PANEL	Repair	396.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,530.00	5,592.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,623.75	1,398.00
Total Parts (\$\$)	7,906.25	4,194.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS,STRAIGHTEN REAR BOTH CHASSIS,REAR SPARE TYRE FLOOR PANEL,CUT/WELD REAR PANEL,REMOVE,REPLACE ACCIDENT PARTS	New	1,200.00	850.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS,PEARL	New	1,200.00	980.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO RESET CHECK LIGHT	New	200.00	50.00
5	TO TRANSFER REAR BUMPER SENSOR	New	100.00	50.00
6	TO 4 WHEEL ALIGNMENT	New	100.00	0.00
7	TO REMOVE,REPAIR REAR EXHAUST PIPE	New	100.00	0.00
8	TO TUFF-KOTE	New	150.00	60.00
9	TO REMOVE,REFIT GARNISH,CARPET,CUSHION,REAR SEAT AND RELATED PARTS	New	200.00	80.00
Gross Labour Cost (\$)			3,300.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >