

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001495/EVY3Q2**Date:** 09/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00076532100

Claimant Vehicle No : SMJ6678Z **Insured Vehicle No :** SMY8092X

Date of Loss: 13/02/2022 Nature of Claim: TP Claim No: SNM22D201132/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ6678Z**

Make & Model: LEXUS UX200, 2.0 LUXURY (A) Engine No: M20AN010242

Reg. Date: 15/03/2019 (Man. Year: 2018) Chassis No: JTHY35BHX02005705

Colour: Green Odometer: 100302 km

Engine Capacity: 1987 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,704.60	1,809.00	2,895.60	61.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,102.50	2,257.50	2,845.00	55.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,807.10	4,066.50	5,740.60	58.54
+ GST 7.00/7.00% (S\$)	686.50	284.66	401.84	58.53
Nett Amount (S\$)	10,493.60	4,351.16	6,142.44	58.54

INSPECTION

Date of Assignment: 16/02/2022

Date Inspected: 17/02/2022 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Mar 2022)
Parts:	M1-SUV	LEXUS UX200 2.0 LUXURY (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ6678Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*REAR NO PLATE	Cut	96.00 FS	*96.00 FS
3	1		*COVER ,RR BUMPER	Crushed	844.40 FS	*844.40 FS
4	1		*COVER ,RR BUMPER	Cut	456.70 FS	*456.70 FS
5	13		*BUMPER CLIPS	Necessary	55.90 FS	*55.90 FS
6	1		*PLATE ,RR BUMPER	Cut	18.40 FS	*18.40 FS
7	2		*TAPE MOULDING ,NO.1	Necessary	84.20 FS	*84.20 FS
8	1		*REINFORCEMENT	Not Necessary	441.60 FS	*- FS
9	1		*SEAL ,RR BUMPER	Not Necessary	90.10 FS	*- FS
10	1		*SEAL ,RR BUMPER	Not Necessary	90.10 FS	*- FS
11	1		*RETAINER ,RR BUMPER	Not Necessary	179.30 FS	*- FS
12	1		*RETAINER ,RR BUMPER	Not Necessary	179.30 FS	*- FS
13	2		*PAD ,RR BUMPER	Not Necessary	29.20 FS	*- FS
14	2		*PAD ,RR BUMPER	Not Necessary	29.20 FS	*- FS
15	10		*CLIP	Necessary	27.00 FS	*27.00 FS
16	2		*RETAINER ,ULTRASONIC	Necessary	88.20 FS	*88.20 FS
17	2		*RETAINER ,ULTRASONIC	Necessary	88.20 FS	*88.20 FS
18	2		*SENSOR ,ULTRASONIC	Not Necessary	980.20 FS	*- FS
19	1		*REFLECTOR ASSY	Not Necessary	51.60 FS	*- FS
20	1		*MOULDING SUB-ASSY	Not Necessary	387.50 FS	*- FS
21	1		*MOULDING SUB-ASSY	Not Necessary	387.50 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	4,704.60	1,809.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON REAR BUMPER ,REAR PANEL AND FIX NEW PARTS	New	2,165.00	866.00
2	TO SPRAY PAINT ON REAR BUMPER	New	1,855.00	742.00
3	TO REMOVE AND TRANSFER REAR SENSOR TO NEW BUMPER ,REPLACE IF DAMAGE	New	216.50	216.50
4	TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST	New	216.50	216.50
5	TO RESET ECU AND REPROGRAMME	New	216.50	216.50
6	TO REMOVE AND REINSTALL REAR LUGGAGE TRIM ,GARNISH ETC TO ENABLE REPAIR	New	433.00	0.00
Gross Labour Cost (\$\$)			5,102.50	2,257.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >