

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001496/UQY3N2**Date:** 18/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00134772100		
Claimant Vehicle No :	SKS2545B	Insured Vehicle No :	GBD1980U		
Date of Loss:	12/02/2022	Nature of Claim:	TP	Claim No:	SNM22D201126/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS2545B		
Make & Model:	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)	Engine No:	K24W71001854
Reg. Date:	01/04/2015 (Man. Year: 2014)	Chassis No:	JHMRC1890EC204355
Colour:	Red	Odometer:	79400 km
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,777.36	2,243.88	1,533.48	40.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,540.00	400.00	20.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,717.36	3,783.88	1,933.48	33.82
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	5,717.36	3,000.00	2,717.36	47.53
+ GST 7.00/7.00% (S\$)	400.22	210.00	190.22	47.53
Nett Amount (S\$)	6,117.58	3,210.00	2,907.58	47.53

INSPECTION

Date of Assignment:	16/02/2022		
Date Inspected:	24/02/2022	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Mar 2022)

Parts: M1-SUV HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKS2545B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	656.10 FL	*656.10 FL
2	2		*REAR BUMPER SIDE HOLDER-LH/RH	Not Necessary	44.20 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
4	2		*REAR BUMPER REFLECTOR-LH/RH	Not Necessary	90.80 FL	*- FL
5	1		*REAR BOOT	Badly Dented	1,141.90 FL	*1,141.90 FL
6	1		*REAR BOOT OUTER CHROME	Cracked	195.00 FL	*195.00 FL
7	1		*REAR BOOT ODYSSEY GARNISH	Not Necessary	246.50 FL	*- FL
8	1		*REAR BOOT HONDA EMBLEM	Necessary	29.80 FL	*29.80 FL
9	2		*REAR BOOT LAMP-LH/RH	Serviceable	823.20 FL	*- FL
10	1		*REAR BOOT TOP LOCK	Dented/Shorted	203.05 FL	*203.05 FL
11	1		*REAR WINDSCREEN MOULDINGS	Necessary	216.00 FL	*216.00 FL
12	1		*REAR END PANEL	Repair	491.40 FL	*- FL
13	1		*REAR END PANEL TOP GARNISH	Not Necessary	112.50 FL	*- FL
14	1		*REAR BOOT BOTTOM LOCK	Not Necessary	27.00 FL	*- FL
15	2		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
16	1		*REAR WINDSCREEN SPONGE TAPE	Necessary	20.00 FS	*20.00 FS
17	1		*REAR NUMBER PLATE WITH CASING	Serviceable	45.00 FS	*- FS
18	1		*SET REAR BUMPER SENSOR	Shorted	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,640.45	2,739.85
- List Item Discount on L Items 20.00/20.00% (S\$)	863.09	495.97
Total Parts (S\$)	3,777.36	2,243.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS,REMOVE,REPLACE ACCIDENT PARTS	New	800.00	600.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	750.00	680.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE,REFIT REAR WINDSCREEN	New	200.00	120.00
5	TO REMOVE AND REFIT END PANEL GARNISH TO FACILITATE REPAIRS	New	80.00	80.00
6	TO TUFF-KOTE	New	60.00	40.00
Gross Labour Cost (\$)			1,940.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >