

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001505/AYA3Q2**Date:** 18/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700049034
Claimant Vehicle No :	SLQ9518H	Insured Vehicle No :	SLR4335X
Date of Loss:	11/02/2022	Nature of Claim:	TP
		Claim No:	5135452922SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ9518H	Engine No:	PE10503778
Make & Model:	MAZDA CX-5, 2.0 PREMIUM EU6 (A)	Chassis No:	JM6KF2W7AJ0109678
Reg. Date:	27/07/2017 (Man. Year: 2017)	Odometer:	50464 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R19	Rear Tyre Size:	225/55 R19
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,411.20	3,409.20	5,002.00	59.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	960.00	1,140.00	54.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,511.20	4,369.20	6,142.00	58.43
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	10,511.20	3,500.00	7,011.20	66.70
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
		(S\$)	3,900.00	
Liabe Amount (50.00%) (S\$)		1,950.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,957.45		

INSPECTION

Date of Assignment:	15/02/2022	
Date Inspected:	15/02/2022	Inspected At: YSK Auto Workshop (HQ) 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER	Repair	625.10 F	*- FL
2	1		*FRONT LH FENDER ARC GARNISH	Cut	258.30 F	*258.30 FL
3	1		*FRONT LH FENDER ARC GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
4	1		*FRONT LH DOOR	Distorted	1,556.00 F	*1,556.00 FL
5	1		*FRONT LH DOOR LOWER PROTECTOR	Deformed	295.60 F	*295.60 FL
6	1		*FRONT LH DOOR LOCK	Not Necessary	398.40 F	*- FL
7	1		*FRONT LH DOOR WEATHERSTRIPE	Necessary	249.20 F	*249.20 FL
8	2		*FRONT LH DOOR HINGE	Not Necessary	290.20 F	*- FL
9	1		*FRONT LH DOOR CHECK	Not Necessary	130.40 F	*- FL
10	1		*FRONT LH DOOR INNER TRIM BOARD	Cracked	784.10 F	*784.10 FL
11	1		*FRONT LH DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
12	1		*FRONT LH DOOR GLASS REGULATOR GEAR	Damaged	245.60 F	*245.60 FL
13	1		*FRONT LH DOOR GLASS REGULATOR MOTOR	Damaged	326.40 F	*326.40 FL
14	1		*FRONT LH DOOR SPEAKER	Cracked	185.40 F	*185.40 FL
15	1		*FRONT LH DOOR WING MIRROR	Not Necessary	1,049.40 F	*- FL
16	1		*FRONT LH DOOR WING MIRROR COVER	Not Necessary	104.10 F	*- FL
17	1		*FRONT LH DOOR WING MIRROR SIGNAL LAMP	Not Necessary	184.10 F	*- FL
18	1		*REAR LH DOOR	Repair	1,380.50 F	*- FL
19	1		*REAR LH DOOR LOWER PROTECTOR	Cut	298.40 F	*298.40 FL
					Sub Total (\$\$)	8,411.20 4,249.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 839.80
					Total Parts (\$\$)	8,411.20 3,409.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	800.00	400.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	50.00
5	TO TRANSFER FRONT AND REAR DOOR FITTINGS	New	300.00	80.00
Gross Labour Cost (S\$)			2,100.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >