

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 7441X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER RH	BADLY DENTED	1,865.00	1,455.00
1	REAR FUEL DOOR RH	TO REPAIR SEE LABOUR	216.00	-
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	166.30	128.00
1	TAIL LAMP RH	BROKEN	656.30	490.00
4	TAIL LAMP CLIP RH @\$12.00	NOT NECESSARY	48.00	-
1	TAIL LAMP PANEL RH	TO REPAIR SEE LABOUR	211.30	-
1	REAR BUMPER	TORN	3,265.00	1,202.00
1	REAR BUMPER RETAINER RH	BENT	166.20	66.00
	LESS 10% DISCOUNT		-	-334.10
			6,594.10	3,006.90
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
2	WINDSCREEN SEALANT @\$24.00 (SN)	NECESSARY	48.00	40.00
1	BOOTLID (NPA) (SN)	NOT NECESSARY	-	-
1	END PANEL (NPA) (SN)	NOT NECESSARY	-	-
1	REAR DOOR RH (NPA) (SN)	NOT NECESSARY	-	-
			328.00	40.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIT NECESSARY PARTS. INCLUSIVE OF THE REPAIR OF REAR FUEL DOOR RH & TAIL LAMP PANEL RH.		1,000.00	600.00
	SPRAY PAINT ON THE AFFECTED AREAS.		800.00	600.00
	ANTI-RUST COATING.		100.00	30.00
	WIRING.		40.00	20.00
	TO REMOVE & REFIT WINDSCREEN.		180.00	120.00
	TO REMOVE & REFIT REVERSE SENSOR.		150.00	40.00
	TO REMOVE & REFIT CUSHION & UPHOSTERY.		250.00	80.00

Report Ref No. CS/AIS22001512/Uncm4



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

3,600.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE & REFIT FUEL TANK.		250.00	60.00
			2,770.00	1,550.00
	GRAND TOTAL		9,692.10	4,596.90

Report Ref No. CS/AIS22001512/Uncm4

**RECOMMENDED COST OF LUMP SUM REPAIRS** 

(TO ITS PRE-ACCIDENT CONDITION)

CHUA KANG SENG

**Licensed Appraiser**