

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22001517/ENY3E2

Date: 12/07/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00098162100		
Claimant Vehicle No :	SMP7113Z	Insured Vehicle No :	GBK5965B		
Date of Loss:	11/02/2022	Nature of Claim:	TP	Claim No:	SNM22D201165/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP7113Z	Engine No:	L15B4458453
Make & Model:	HONDA FREED, 1.5 (A)	Chassis No:	GB51114468
Reg. Date:	10/10/2019 (Man. Year: 2019)	Odometer:	25523 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,082.72	5,455.96	4,626.76	45.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	2,330.00	1,370.00	37.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,782.72	7,785.96	5,996.76	43.51
+ GST 7.00/7.00% (\$\$)	964.79	545.02	419.77	43.51
Nett Amount (\$\$)	14,747.51	8,330.98	6,416.53	43.51

INSPECTION

Date of Assignment:	17/02/2022	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	16/02/2022 Inspected At:	Blk 3 Pioneer Road North, #01-18
Estimated Period of Repair:	7.0 days	Singapore 628457

Adjuster: CHEN TSUE YEE

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2022)
Parts:	M1-MPV	HONDA FREED 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP7113Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	897.00 FL	*897.00 FL
2	1		*FRT BUMPER RETAINER (LH)	Broken	19.50 FL	*19.50 FL
3	1		*FRT BUMPER LOWER GRILLE	Not Necessary	180.00 FL	*- FL
4	1		*FRT BUMPER REINFORCEMENT	Dented	373.20 FL	*373.20 FL
5	10		*FRT BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
6	1		*FRT GRILLE ASSY (COMPLETE)	Broken	883.80 FL	*883.80 FL
7	10		*FRT GRILLE CLIPS	Necessary	30.40 FS	*10.00 FS
8	1		*FRT HEADLAMP (LH)	Not Necessary	1,453.30 FL	*- FL
9	1		*FRT HEADLAMP LWR BRKT LH	Not Necessary	30.50 FL	*- FL
10	1		*FRT BONNET LOCK	Not Necessary	121.30 FL	*- FL
11	1		*FRT SUPPORT PANEL	Repair	606.40 FL	*- FL
12	1		*FRT SUPPORT AIR GUIDE LH	Not Necessary	35.20 FL	*- FL
13	1		*AIRCON CONDENSER	Not Necessary	985.00 FL	*- FL
14	1		*RADIATOR ASSY	Not Necessary	1,383.10 FL	*- FL
15	1		*REAR BUMPER	Dented	819.40 FL	*819.40 FL
16	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
17	1		*REAR BOOT LID	Dented	1,132.90 FL	*1,132.90 FL
18	1		*REAR BOOT INNER TRIM BOARD	Crushed	288.00 FL	*288.00 FL
19	1		*REAR BOOT CENTER TRIM	Crushed	320.40 FL	*320.40 FL
20	1		*REAR NUMBER PLATE LAMP	Not Necessary	42.80 FL	*- FL
21	1		*REAR BOOT EMBLEM	Necessary	32.10 FL	*32.10 FL
22	1		*REAR BOOT FREED LOGO	Necessary	55.00 FL	*55.00 FL
23	2		*REAR BOOT LAMP	Not Necessary	726.60 FL	*- FL
24	1		*REAR BOOT LOCK	Bent	157.10 FL	*157.10 FL
25	1		*REAR BOOT WEATHERSTRIPE	Crushed	168.00 FL	*168.00 FL
26	1		*REAR WINDSCREEN MOULDING	Necessary	118.30 FL	*118.30 FL
27	1		*REAR END PANEL	Dented	423.70 FL	*423.70 FL
28	1		*REAR END PANEL TOP GARNISH	Crushed	74.30 FL	*74.30 FL
29	1		*FRT NUMBER PLATE	Broken	35.00 FS	*35.00 FS
30	1		*REAR NUMBER PLATE	Not Necessary	35.00 FS	*- FS
31	1		*REAR WINDSCREEN GUM	Necessary	40.00 FS	*40.00 FS
32	1		*COOLANT	Not Necessary	40.00 FS	*- FS
33	1		*REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
34	1		*REAR BOOT OUTER HANDLE	Broken	25.00 FL	*25.00 FL
35	1		*REAR FLOOR MAT	Crushed	600.00 FL	*600.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,488.30	6,748.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,405.58	1,292.74
Total Parts (\$\$)	10,082.72	5,455.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK FRT BONNET, FRT FENDER LH, WELD, REMOVE & REPLACE ABOVE PARTS	New	1,400.00	800.00
2	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	New	1,400.00	800.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO REMOVE & REPLACE REAR WINDSCREEN	New	120.00	120.00
5	TO TOP UP AIRCON GAS	New	100.00	0.00
6	TO APPLY ANTI RUST COATING	New	100.00	30.00
7	TO KNOCK, SPRAY PAINTING ON REAR SPARE TYRE PANEL	New	400.00	400.00
8	TO REMOVE FIX UPHOLSTERY R&R REAR SEAT & CARPET	New	150.00	150.00
Gross Labour Cost (\$\$)			3,700.00	2,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >