

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001518/BQY3N2**Date:** 10/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00007452100

Claimant Vehicle No : SMP6771E **Insured Vehicle No :** SMX402T

Date of Loss: 11/02/2022 Nature of Claim: TP Claim No: SNM22D201072/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP6771E**

Make & Model: TOYOTA NOAH HYBRID, 1.8 X CVT (A) Engine No: 2ZR0E29508

Reg. Date: 09/10/2019 (Man. Year: 2019) Chassis No: ZWR800403496

Colour: Black Odometer: 167192 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Davanti 5 mm Rear Left Side: Davanti 5 mm

Front Right Side: Davanti 5 mm Rear Right Side: Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,297.80	4,728.75	7,569.05	61.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	2,060.00	3,040.00	59.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	17,397.80	6,788.75	10,609.05	60.98
+ GST 7.00/7.00% (\$\$)	1,217.85	475.21	742.64	60.98
Nett Amount (\$\$)	18,615.65	7,263.96	11,351.69	60.98

INSPECTION

Date of Assignment: 16/02/2022

Date Inspected: 21/02/2022 Inspected At: 160 SIN MING DR
#01-14 SIN MING AUTO CITY
SINGAPORE 575722
REPAIRER: TEAM AUTOPRO PTE LTD

Estimated Period of Repair: 8.0 days

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Mar 2022)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP6771E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,812.70 FL	*1,295.00 FL
2	1		*TAILGATE EMBLEM HYBRID	Necessary	158.20 FL	*85.80 FL
3	1		*TAILGATE INNER LOCK	Jammed	452.60 FL	*452.60 FL
4	1		*TAILGATE INNER LOCK STICKER	Not Damaged	45.00 FL	*- FL
5	1		*TAILGATE OUTER CHROME GARNISH	Broken	767.80 FL	*687.00 FL
6	1		*TAILGATE INNER TRIM BOARD	Broken	570.30 FL	*425.00 FL
7	1		*TAILGATE INNER HANDLE	Not Damaged	74.80 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Torn	375.10 FL	*295.00 FL
9	1		*TAILGATE BUZZER	No such part	165.00 FL	*- FL
10	1		*TAILGATE ANTENNA SENSOR	Broken	180.00 FL	*180.00 FL
11	1		*TAILGATE WINDSCREEN MOULDING	Necessary	238.00 FL	*185.00 FL
12	1		*REAR BUMPER	Broken	1,339.31 FL	*1,025.00 FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	291.60 FL	*150.00 FL
14	2		*REAR BUMPER BRACKET	No such part	130.40 FL	*- FL
15	1		*REAR BUMPER REFLECTOR	O/s Broken	251.20 FL	*125.00 FL
16	1		*REAR BUMPER TOW CAP	Not Damaged	28.10 FL	*- FL
17	1		*REAR END PANEL	Dented	985.70 FL	*691.00 FL
18	1		*REAR END PANEL TOP GARNISH	Broken	148.60 FL	*148.60 FL
19	1		*SPARE TYRE PANEL	Not Damaged	935.65 FL	*- FL
20	1		*SPARE TYRE PANEL TOP BOARD	Not Damaged	791.68 FL	*- FL
21	2		*REAR FENDER INNER TRIM BOARD	Not Damaged	1,300.00 FL	*- FL
22	2		*TAILLAMP	Not Damaged	1,770.00 FL	*- FL
23	2		*TAILLAMP LOWER GARNISH	Not Damaged	390.00 FL	*- FL
24	2		*TAILLAMP LOWER GARNISH RETAINER	Not Damaged	302.00 FL	*- FL
25	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
26	1		*TAILGATE SEALANT	Necessary	100.00 FS	*30.00 FS
27	1		*TAILGATE OUTER CHROME GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
28	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*20.00 FS
29	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
30	1		*TAILGATE WINDSCREEN CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
32	1		*TAILGATE WINDSCREEN PRIMER & CLEANER	Not Necessary	60.00 FS	*- FS
33	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
35	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
36	1		*SPARE TYRE PANEL SEALANT	Not Necessary	100.00 FS	*- FS
37	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
38	2		*TAILLAMP CLIPS	Not Necessary	100.00 FS	*- FS
39	2		*TAILLAMP SEAL	Not Necessary	120.00 FS	*- FS
40	1		*TAILLAMP LOWER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
42	2		*REVERSE SENSOR	Short Circuit	500.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,673.74	6,165.00
- List Item Discount on L Items 25.00/25.00% (S\$)	3,375.94	1,436.25

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	12,297.80
						4,728.75
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REVERSE SENSOR	New	100.00	60.00
4	R&R REVERSE CAMERA	New	100.00	0.00
5	CHECK WIRING	New	100.00	0.00
6	UPHOLSTERY	New	300.00	0.00
7	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
8	PANEL BEATING	New	1,800.00	1,000.00
9	RUST PROOFING	New	200.00	0.00
10	SPRAY PAINTING	New	1,800.00	800.00
Gross Labour Cost (\$\$)			5,100.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >