

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001521/BQY3N2**Date:** 25/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00177892100		
Claimant Vehicle No :	SND1711M	Insured Vehicle No :	SLC2604L		
Date of Loss:	13/02/2022	Nature of Claim:	TP	Claim No:	SNM22D201151/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND1711M		
Make & Model:	MERCEDES-BENZ C180 BLUE EFFICIENCY, 1.6 (A)	Engine No:	27491030026176
Reg. Date:	11/01/2013 (Man. Year: 2012)	Chassis No:	WDD2040312A793609
Colour:	Black	Odometer:	170472 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40ZR18	Rear Tyre Size:	225/40ZR18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,989.24	12,326.35	12,662.89	50.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,020.00	2,380.00	3,640.00	60.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,009.24	14,706.35	16,302.89	52.57
Approved Total (Overridden) (\$\$)		11,750.00		
(\$\$)	31,009.24	11,750.00	19,259.24	62.11
+ GST 7.00/7.00% (\$\$)	2,170.65	822.50	1,348.15	62.11
Nett Amount (\$\$)	33,179.89	12,572.50	20,607.39	62.11

INSPECTION

Date of Assignment:	14/04/2022		
Date Inspected:	21/02/2022	Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	8.0 days		

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 May 2022)

Parts: 143 MERCEDES-BENZ C180 BLUE EFFICIENCY 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SND1711M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,520.00 FL	*1,520.00 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	55.60 FL	*55.60 FL
3	1		*BOOTLID LOCK	Jammed	315.00 FL	*254.00 FL
4	1		*BOOTLID WEATHERSTRIP	Torn	197.00 FL	*197.00 FL
5	1		*REAR BUMPER	Broken	1,170.00 FL	*1,170.00 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FL	*30.00 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	664.00 FL	*545.20 FL
8	1		*REAR BUMPER RH SIDE BRACKET	Bent	45.00 FL	*45.00 FL
9	1		*REAR BUMPER LH SIDE BRACKET	Bent	45.00 FL	*45.00 FL
10	1		*REAR BUMPER CENTRE BRACKET	Bent	131.70 FL	*131.70 FL
11	1		*REAR BUMPER RH LOWER BRACKET	Necessary	49.00 FL	*49.00 FL
12	1		*REAR BUMPER LH LOWER BRACKET	Necessary	49.00 FL	*49.00 FL
13	1		*REAR BUMPER LOWER GARNISH	Broken	344.50 FL	*313.00 FL
14	1		*REAR BUMPER LOWER COVER	No such part	178.00 FL	*- FL
15	1		*LH TAILLAMP ASSY	Broken	610.10 FL	*610.10 FL
16	1		*LH TAILLAMP LOWER BRACKET	Broken	86.00 FL	*49.00 FL
17	1		*LH TAILLAMP PANEL	Dented	173.00 FL	*173.00 FL
18	1		*END PANEL	Dented	1,188.00 FL	*1,018.00 FL
19	1		*END PANEL INNER GARNISH	Broken	156.00 FL	*118.80 FL
20	1		*SPARE TYRE PANEL TOP COVER	Broken	315.00 FL	*285.00 FL
21	1		*SPARE TYRE PANEL	Not Damaged	738.00 FL	*- FL
22	1		*SPARE TYRE PANEL TOOL TRAY	Not Damaged	187.00 FL	*- FL
23	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	1,167.80 FL	*198.00 FL
24	1		*REAR LH FENDER	Bent	2,395.60 FL	*1,800.00 FL
25	1		*REAR LH FENDER INNER TRIM BOARD	Not Damaged	367.30 FL	*- FL
26	1		*SET REAR LH FENDER INNER TRIM BOARD CLIPS	Not Damaged	70.00 FL	*- FL
27	1		*REAR LH FENDER SPLASH SHIELD	Torn	144.00 FL	*144.00 FL
28	1		*SET REAR LH FENDER SPLASH SHIELD CLIPS	Necessary	60.00 FL	*30.00 FL
29	1		*LH REAR KNUCKLE ARM	Not Damaged	1,020.30 FL	*- FL
30	1		*LH REAR WHEEL BEARING	Not Damaged	445.00 FL	*- FL
31	1		*LH REAR UPPER ARM	Not Damaged	299.10 FL	*- FL
32	1		*LH REAR SHOCK ABSORBER	Not Damaged	388.70 FL	*- FL
33	1		*LH REAR CAMBER ARM	Not Damaged	287.00 FL	*- FL
34	1		*LH REAR CONTROL ARM	Not Damaged	322.50 FL	*- FL
35	1		*LH REAR THRUST ARM	Not Damaged	287.00 FL	*- FL
36	1		*LH REAR LOWER ARM	Not Damaged	478.60 FL	*- FL
37	1		*EXHAUST SILENCER	Bent	1,428.50 FL	*1,058.00 FL
38	1		*EXHAUST SILENCER GASKET	Necessary	54.00 FL	*54.00 FL
39	1		*EXHAUST SILENCER CHROME FINISHER	Dented	206.00 FL	*206.00 FL
40	1		*PASSENGER HEADREST ASSY	Activated	930.00 FL	*930.00 FL
41	1		*PASSENGER SEAT BELT	Not Damaged	733.00 FL	*- FL
42	1		*PASSENGER SEAT BELT BUCKLE	Not Damaged	155.00 FL	*- FL
43	1		*DRIVER HEADREST ASSY	Activated	930.00 FL	*930.00 FL
44	1		*DRIVER SEAT BELT	Not Damaged	733.00 FL	*- FL
45	1		*DRIVER SEAT BELT BUCKLE	Not Damaged	155.00 FL	*- FL
46	1		*REAR RH PASSENGER SEAT BELT	Not Damaged	733.00 FL	*- FL

Report was unsubmitted during this print-out.

5/25/22, 9:28 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR RH PASSENGER SEAT BELT BUCKLE	Not Damaged	155.00 FL	*- FL
48	1		*REAR LH PASSENGER SEAT BELT	Not Damaged	733.00 FL	*- FL
49	1		*REAR LH PASSENGER SEAT BELT BUCKLE	Not Damaged	155.00 FL	*- FL
50	1		*DRIVER SEAT BELT BUCKLE	Not Damaged	155.00 FL	*- FL
51	1		*SRS CONTROL UNIT	Activated	1,853.30 FL	*933.00 FL
52	1		*RH TAILLAMP ASSY	Broken	615.00 FL	*610.10 FL
53	1		*LH REAR SPORT RIM	Not Damaged	1,050.00 FS	*- FS
54	1		*LH REAR TYRE	Not Damaged	450.00 FS	*- FS
55	1		*BRAKE FLUID	Not Necessary	60.00 FS	*- FS
56	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
57	1		*REAR LH FENDER JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
58	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*40.00 FS
59	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					27,563.60	13,681.50
- List Item Discount on L Items 10.00/10.00% (\$\$)					2,574.36	1,355.15
Total Parts (\$\$)					24,989.24	12,326.35
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	2,000.00	1,200.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,400.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	150.00	0.00
5	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	120.00
6	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR	New	100.00	60.00
7	REMOVE AND REPLACE REAR INNER TRIMS,GARNISH,ROOF LINING,BOARDS,SEATS AND CARPET TO ASSIST REPAIR	New	450.00	0.00
8	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	180.00	80.00
9	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	350.00	0.00
10	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
11	REMOVE AND REINSTALL FUEL TANK,PIPES AND SENSORS TO ASSIST REPAIR	New	180.00	0.00
12	REMOVE AND REPLACE FRONT AND REAR SEAT BELTS,BUCKLES AND CONTROL UNIT TO ASSIST REPAIR	New	480.00	0.00
13	RESET AND DIAGNOSE FAULT CODES AND CONTROL UNIT	New	350.00	120.00
Gross Labour Cost (\$)			6,020.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >