

Vehicle Damage Assessment Report for [SFG1798S]

Estimate Created: 04/07/2022 01:01 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 07/09/2022 02:51 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number	MFL2022D0000842
Claim Type	TP		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Subaru	Model	Forester
Engine Type			
License Plate Number	SFG1798S	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	48,622.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$1300.00 with 3 days for repair

Insurlogic 1 (07/09/2022 02:49)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REAR BUMPER		1	540.30	-20.00 %	432.24
REAR BUMPER REINFORCEMENT		1	320.40	-20.00 %	256.32
Parts Subtotal					688.56

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REVERSE SENSOR		1.0	200.00	0.00 %	200.00
Materials Subtotal					200.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
REPLACE REAR BUMPER AND REINFORCEMENT	RnR	300.00	0.00 %	300.00
REMOVE AND REFIX REVERSE SENSOR	RnR	50.00	0.00 %	50.00
CHECK WIRING	RnR	15.00	0.00 %	15.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ACCIDENT AFFECTED PORTION	Full spray	400.00	0.00 %	400.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 365.00

Paint Labor Subtotal 400.00

Labor Subtotal 765.00

Summary

Repair Cost	1,653.56
Discount(21 %)	(353.56)
	1,300.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	1,300.00