

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001524/TVY3N2**Date:** 26/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00187982000	
Claimant Vehicle No :	SJU9389R	Insured Vehicle No :	SMZ252Z	
Date of Loss:	11/02/2022	Nature of Claim:	TP	Claim No: SNM22D201098/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU9389R		Engine No:	4A910127559
Make & Model:	MITSUBISHI LANCER, 1.5 (A)		Chassis No:	JMYSRCY2AAU000517
Reg. Date:	05/01/2010 (Man. Year: 2009)		Odometer:	185160 km
Colour:	Black			
Engine Capacity:	1499 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,277.50	8,410.10	9,867.40	53.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,560.00	2,260.00	3,300.00	59.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,837.50	10,670.10	13,167.40	55.24
Approved Total (Overridden) (\$\$)		7,800.00		
Nett Amount (\$\$)	23,837.50	7,800.00	16,037.50	67.28

INSPECTION

Date of Assignment:	11/03/2022	EVEREST MOTOR GARAGE PTE LTD (HQ) 25 KAKI BUKIT ROAD 4, #05-80, SINGAPORE 417800 Singapore 417800
Date Inspected:	17/02/2022 Inspected At:	
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2022)
Parts:	143	MITSUBISHI LANCER 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU9389R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CUSTOM MAKE)	Cracked	2,850.00 FL	*1,400.00 FL
2	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	750.00 FL	*326.00 FL
3	2		*FRONT BUMPER SIDE HOLDER	Deformed	170.00 FL	*170.00 FL
4	1		*FRONT BONNET	Bent	1,800.00 FL	*850.00 FL
5	1		*FRONT BONNET LOCK ASSY	Not Necessary	480.00 FL	*- FL
6	1		*FRONT BUMPER LOGO EMBLEM	Necessary	125.00 FL	*40.00 FL
7	2		*FRONT BONNET HINGE	Repair	220.00 FL	*- FL
8	1		*FRONT HEADLAMP LHS	Cracked	1,100.00 FL	*671.00 FL
9	1		*FRONT BUMPER LHS UNDER COVER	Cut	110.00 FL	*110.00 FL
10	1		*FRONT BUMPER UNDER COVER	Torn	185.00 FL	*185.00 FL
11	1		*FRONT ENGINE UNDER COVER	Not Necessary	240.00 FL	*- FL
12	1		*LHS BODY ROCKER PANEL GARNISH (CUSTOM MAKE)	Repair	540.00 FL	*- FL
13	1		*SET FRONT FENDER (CUSTOM MAKE)	Cracked	1,800.00 FL	*900.00 FL
14	1		*LHS FRONT FENDER INNER TRIM	Missing	320.00 FL	*196.00 FL
15	1		*FRONT SUPPORT PANEL	Repair	980.00 FL	*- FL
16	1		*FRONT LHS SHOCK ABSORBER	Bent	840.00 FL	*417.00 FL
17	1		*FRONT LHS WHEEL HUB ASSY	Bent	650.00 FL	*336.00 FL
18	1		*FRONT LHS WHEEL HUB BEARING	Bent	540.00 FL	*195.00 FL
19	1		*FRONT LHS LOWER CONTROL ARM	Bent	380.00 FL	*291.00 FL
20	1		*FRONT LHS LINK ARM	Bent	125.00 FL	*125.00 FL
21	1		*FRONT LHS DRIVE SHAFT	Not Necessary	750.00 FL	*- FL
22	1		*STEERING RACK AND PINION	Bent	1,850.00 FL	*1,850.00 FL
23	1		*FRONT LHS RIM	Cut	1,100.00 FS	*500.00 FS
24	1		*FRONT HIGH PERFORMENT AIR FILTER	Not Necessary	280.00 FS	*- FS
25	1		*FRONT ENGINE SUBFRAME	Bent	1,650.00 FL	*565.00 FL
26	1		*FRONT ANTI ROLL BAR	Bent	320.00 FL	*162.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,155.00	9,289.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,877.50	878.90
Total Parts (\$)	18,277.50	8,410.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE SUB FRAME	New	600.00	100.00
2	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS	New	1,800.00	800.00
3	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED	New	2,000.00	1,100.00
4	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	80.00	30.00
5	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO SPECIFICATION	New	300.00	0.00
6	TO PROVIDE ANTI RUST TREATMENT TO AFFECTED AREAS	New	180.00	30.00
7	TO REMOVE AND REFIX A/C CONDENSER AND RADIATOR SO AS TO FACILITATE REPLACE OD SUPPORT PANEL	New	180.00	0.00
8	TO REMOVE AND REPLACE STEERING RACK AND PINION	New	240.00	100.00
9	TO REMOVE AND REPLACE OF FRONT LHS UNDERCARRIAGE SYSTEM	New	180.00	100.00
Gross Labour Cost (\$\$)			5,560.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >