

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001526/EVY3N2**Date:** 23/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00130222100

**Claimant Vehicle No :** SMN349S **Insured Vehicle No :** SMC6524Z

Date of Loss: 24/01/2022 Nature of Claim: TP Claim No: SNM22D200700/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMN349S**

Make & Model: HONDA FREED, 1.5 (A) Engine No: LEB5607286

Reg. Date: 23/07/2019 (Man. Year: 2018) Chassis No: GB71072759

Colour: White Odometer: 94799 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15

Front Left Side: Goodyear 4 mm Rear Left Side: Goodyear 4 mm

Front Right Side: Goodyear 4 mm Rear Right Side: Goodyear 4 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,032.20	2,705.52	1,326.68	32.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,400.00	550.00	28.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,982.20</b>	<b>4,105.52</b>	<b>1,876.68</b>	<b>31.37</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,300.00</b>		
<b>(S\$)</b>	5,982.20	3,300.00	2,682.20	44.84
<b>+ GST 7.00/7.00% (S\$)</b>	418.75	231.00	187.75	44.84
<b>Nett Amount (S\$)</b>	<b>6,400.95</b>	<b>3,531.00</b>	<b>2,869.95</b>	<b>44.84</b>

**INSPECTION**

Date of Assignment: 16/02/2022

Date Inspected: 17/02/2022 Inspected At: Ethoz Group Ltd (HQ)  
30 Bukit Batok Crescent  
Singapore 658075

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2022)
Parts:	M1-MPV	HONDA FREED 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN349S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	780.00 FL	*780.00 FL
2	2		*REAR BUMPER RETAINER	Broken	54.00 FL	*54.00 FL
3	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
4	1		*TAILGATE	Dented	2,175.00 FL	*1,207.90 FL
5	1		*TAILGATE LOCK	Not Necessary	135.00 FL	*- FL
6	1		*EMBLEM-FREED	Necessary	63.00 FL	*63.00 FL
7	1		*EMBLEM-HYBRID	Necessary	82.00 FL	*82.00 FL
8	1		*REAR WINDSCREEN MOULDING	Necessary	90.00 FL	*90.00 FL
9	1		*END PANEL (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*FRONT BUMPER	Crushed	745.00 FL	*745.00 FL
11	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	435.00 FL	*- FL
13	1		*REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
14	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
15	1		*FRONT NUMBER PLATE	Not Necessary	35.00 FS	*- FS
					Sub Total (S\$)	4,964.00 3,321.90
					- List Item Discount on L Items 20.00/20.00% (S\$)	931.80 616.38
					Total Parts (S\$)	4,032.20 2,705.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO FACILITATE REPAIR	New	800.00	600.00
2	TO RESPRAY AFFECTED AREAS	New	800.00	600.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	50.00	30.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
5	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	New	150.00	50.00
<b>Gross Labour Cost (\$)</b>			<b>1,950.00</b>	<b>1,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >