



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 5385C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (N)	DENTED / DEFORMED	860.00	693.10
1	REAR BUMPER REINFORCEMENT (N)	TO REPAIR SEE LABOUR	795.00	-
2	REAR BUMPER SIDE BRACKET @\$98.00 (N)	BENT	196.00	116.00
1	X TRIAL REAR BUMPER CHROME (N)	BENT	580.00	480.00
1	REAR BUMPER CHROME MOULDING (N)	CRACKED	498.00	171.30
1	REAR BOOTH LID (N)	TO REPAIR SEE LABOUR	1,150.00	-
1	X TRIAL REAR BOOTH LID EMBLEM (N)	NECESSARY	115.00	105.00
1	LOGO REAR BOOTH LID EMBLEM (N)	NOT NECESSARY	98.00	-
	LESS 10% DISCOUNT		-	-156.54
			4,292.00	1,408.86
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	220.00	200.00
			220.00	200.00
	<u>LABOUR</u>			
	CAR CERAMIC COATING.		150.00	150.00
	TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS.TO SPRAY PAINT ALL DAMAGED PARTS.		680.00	580.00
	TO KNOCK AND REPAIR DAMAGED PARTS.TO REMOVE AND CHANGE ALL DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR BOOTH LID.		720.00	600.00
	TO CHECK ALL WIRING,TO REVERSE SENSOR WIRING TO CHECK LIGHTINGS.		160.00	50.00
			1,710.00	1,380.00
	GRAND TOTAL		6,222.00	2,988.86

Report Ref No. CS/SMO22001530/Uqf3n2



RECOMMENDED COST OF REPAIRS			2,988.86
-----------------------------	--	--	-----------------

Report Ref No. CS/SMO22001530/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.