

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001533/AVY3E2

Date: 29/06/2022

REFERENCE

Insured/Claimant: DHARMARAJ MELANCIA SNEGA LATHA
Date of Loss: 01/02/2022

Policy No: 1900009059-03
Nature of Claim: OD

Claim No: 6720368773SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH7690R**
Make & Model: AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A) Engine No: CVK075880
Reg. Date: 30/01/2019 (Man. Year: 2018) Chassis No: WAUZZZF43KA029160
Colour: Bronze Odometer: 12183 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$134,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,611.00	12,245.84	11,365.16	48.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,622.00	3,022.00	5,600.00	64.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,233.00	15,267.84	16,965.16	52.63
- Excess (S\$)	1,300.00	1,300.00	0.00	0.00
(S\$)	30,933.00	13,967.84	16,965.16	54.84
+ GST 7.00/7.00% (S\$)	2,165.31	977.75	1,187.56	54.84
Nett Amount (S\$)	33,098.31	14,945.59	18,152.72	54.84

INSPECTION

Date of Assignment: 17/02/2022

Date Inspected: 16/02/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Cracked	219.00 FS	*174.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	254.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	72.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,478.00 FS	*1,182.40 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	151.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	139.00 FS	*110.80 FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
11	1		*FRONT BUMPER BRACKET - RH	Not Necessary	254.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	41.00 FS	*- FS
13	1		*FRONT BUMPER TOP COVER	Cracked	143.00 FS	*114.00 FS
14	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
15	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
16	1		*FRONT BUMPER BRACKET LOCK CARRIER	Cracked	154.00 FS	*122.80 FS
17	1		*FRONT BUMPER SUPPORT - LH / RH	O/S Damaged	64.00 FS	*25.44 FS
18	4		*POP RIVET	Necessary	4.00 FS	*2.88 FS
19	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	244.00 FS	*- FS
20	4		*FRONT BUMPER PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
21	1		*SET FRONT BUMPER WIRING	Not Necessary	567.00 FS	*- FS
22	1		*HORN - RH	Not Necessary	139.00 FS	*- FS
23	1		*HORN SUPPORT - RH	Not Necessary	33.00 FS	*- FS
24	1		*BONNET	Dented	3,425.00 FS	*2,740.00 FS
25	1		*BONNET ATTACHMENT PARTS	Not Necessary	431.00 FS	*- FS
26	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	31.00 FS	*24.24 FS
27	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	62.00 FS	*48.96 FS
28	1		*BONNET STRIKER - RH	Not Necessary	56.00 FS	*- FS
29	1		*BONNET LOCK	Not Necessary	228.00 FS	*- FS
30	1		*BONNET BOWDEN CABLE	Not Necessary	64.00 FS	*- FS
31	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
32	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
33	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
34	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	262.00 FS	*- FS
35	1		*FRONT WHEEL SPOILER	Not Necessary	82.00 FS	*- FS
36	1		*FRONT WHEEL SPOILER LOWER - RH	Not Necessary	40.00 FS	*- FS
37	1		*HEADLIGHT - RH	Cut	7,693.00 FS	*6,154.40 FS
38	1		*LIFT CYLINDER - RH	Not Necessary	231.00 FS	*- FS
39	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
40	1		*LOCK CARRIER	Not Necessary	1,127.00 FS	*- FS
41	1		*LOCK CARRIER SUPPORT - RH	Not Necessary	43.00 FS	*- FS
42	1		*A/C CONDENSER	Not Necessary	683.00 FS	*- FS
43	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
44	1		*CHARGED AIR COOLER	Not Necessary	654.00 FS	*- FS
45	1		*CHARGED AIR COOLER PRESSURE HOSE	Not Necessary	413.00 FS	*- FS
46	1		*RADIATOR AIR GUIDE OUTER - RH	Torn	32.00 FS	*25.60 FS
47	1		*RADIATOR AIR GUIDE INNER - RH	Torn	14.00 FS	*10.88 FS
48	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
49	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
50	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
51	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **23,611.00** **12,245.84**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE VACUUM AND REGAS	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL PARTS REMOVED	New	4,200.00	1,000.00
5	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			8,622.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >