

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI22001535/AQF3E2

Date: 20/05/2022

### REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000495		
Claimant Vehicle No :	SGV8835G	Insured Vehicle No :	SJQ9154Y		
Date of Loss:	29/01/2022	Nature of Claim:	TP	Claim No:	M2200799

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV8835G	Engine No:	P520275705
Make & Model:	MAZDA 3, 1.5 HATCHBACK L SP.6EAT (A)	Chassis No:	JM6BM44A8G0308597
Reg. Date:	24/06/2015 (Man. Year: 2015)	Odometer:	72438 km
Colour:	Bronze		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,542.20	9,548.96	6,993.24	42.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	2,110.00	1,620.00	43.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,272.20</b>	<b>11,658.96</b>	<b>8,613.24</b>	<b>42.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>20,272.20</b>	<b>9,300.00</b>	<b>10,972.20</b>	<b>54.12</b>

### INSPECTION

Date of Assignment:	17/02/2022	ADVANCE AUTO GARAGE (23 KAKI BUKIT) (HQ)
Date Inspected:	05/02/2022 Inspected At:	25 KAKI BUKIT AVE 4 #04-01 VICOM KAKI BUKIT
Estimated Period of Repair:	6.0 days	Singapore 415933

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 May 2022)
Parts:	144	MAZDA 3 1.5 HATCHBACK L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGV8835G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER	Deformed	1,031.70 F	-	*1,031.70 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	-	*30.00 FS
3	2		*FRONT BUMPER SIDE HOLDER	Necessary	68.20 F	-	*68.20 FL
4	2		*HEADLAMP	Cracked	4,508.00 F	-	*4,508.00 FL
5	1		*FRONT FENDER	N/S Dented / O/S Repair	679.80 F	-	*339.90 FL
6	1		*FRONT FENDER INNER SHIELD	N/S Deformed	319.60 F	-	*159.80 FL
7	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	-	*30.00 FS
8	1		*FRONT LH DOOR	Dented	1,098.40 F	-	*1,098.40 FL
9	1		*FRONT LH DOOR LOCK	Not Necessary	378.10 F	-	*- FL
10	1		*FRONT LH DOOR WEATHERSTRIPE	Not Necessary	136.90 F	-	*- FL
11	2		*FRONT LH DOOR HINGE	Bent	136.00 F	-	*136.00 FL
12	1		*FRONT LH DOOR INNER TRIM BOARD	Cracked	594.10 F	-	*594.10 FL
13	1		*FRONT LH DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	-	*30.00 FS
14	1		*FRONT LH DOOR GLASS REGULATOR GEAR	Not Necessary	279.40 F	-	*- FL
15	1		*FRONT LH DOOR BLACK TAPE	Necessary	60.00 FS	-	*60.00 FS
16	2		*FRONT WHEEL RIM	Cut	2,160.00 FS	-	*1,100.00 FS
17	1		*FRONT TYRE	N/S Punctured	600.00 FS	-	*200.00 FS
18	2		*FRONT LOWER ARM	Bent	789.00 F	-	*789.00 FL
19	1		*FRONT SHOCK ABSORBER	N/S Bent	691.20 F	-	*345.60 FL
20	1		*FRONT KNUCKLE ARM	N/S Damaged	962.80 F	-	*481.40 FL
21	2		*FRONT WHEEL HUB C/W BEARING	Damaged	478.80 F	-	*478.80 FL
22	2		*FRONT ANTI ROLL BAR LINKAGE	Not Necessary	196.40 F	-	*- FL
23	1		*STEERING RACK AND PINION	Not Necessary	1,161.00 F	-	*- FL
24	1		*WIPER WASHER TANK	Cracked	92.80 F	-	*92.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,542.20	11,573.70
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	2,024.74
Total Parts (S\$)	16,542.20	9,548.96

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,000.00	700.00
2	SPRAY PAINTING	New	1,500.00	800.00
3	WIRING	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	40.00
5	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	80.00
6	TO DISMANTLE FRONT LH AND RH UNDERCARRIAGES	New	680.00	380.00
7	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,730.00</b>	<b>2,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >