LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22001536/DTF3E2

Date: 09/05/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001904871

Claimant Vehicle GN6262P Insured Vehicle No: SLE5728H

Date of Loss: 11/01/2022 Nature of Claim: TP Claim No: 269910

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GN6262P

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2832605

Reg. Date: 23/11/2018 (Man. Year: 2018) Chassis No: JTFAT35Y20K211935

Colour: White Odometer: 70748 km

Engine Capacity: 2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15 Rear Tyre Size: 155 R12 (D)
Front Left Side: Bridgestone 5 mm Rear Left Side: Falken 5/5 mm
Front Right Side: Falken 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		11,534.39	0.00	11,534.39	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		7,050.00	200.00	6,850.00	97.16
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	18,584.39	200.00	18,384.39	98.92
	+ GST 7.00/7.00% (S\$)	1,300.91	14.00	1,286.91	98.92
	Nett Amount (S\$)	19,885.30	214.00	19,671.30	98.92

INSPECTION

Date of Assignment: 17/02/2022

JWG International Pte Ltd (HQ)

Date Inspected: 18/02/2022 Inspected At: Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK

AutoPoint

Singapore 568047

Estimated Period of Repair: 1.0 days

Adjuster: BRYAN TANI Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Apr 2022)

Parts: N/A TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GN6262P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Not Necessary	2,179.00 FL	*- FL
2	4		*TAILGATE HINGE	Not Necessary	410.80 FL	*- FL
3	1		*TAILGATE LOCK LH	Not Necessary	434.62 FL	*- FL
4	1		*TAILGATE STOPPER LH	Not Necessary	143.56 FL	*- FL
5	1		*TAILGATE STOPPER BRACKET LH	Not Necessary	264.18 FL	*- FL
6	1		*TAILGATE DYNA STICKER	Not Necessary	101.00 FL	*- FL
7	2		*TAIL LAMP LH	Not Necessary	907.40 FL	*- FL
8	2		*TAIL LAMP BRACKET LH	Not Necessary	271.64 FL	*- FL
9	1		*REAR END PANEL	Not Necessary	1,074.59 FL	*- FL
10	6		*SIDEGATE HINGE	Not Necessary	1,104.00 FL	*- FL
11	1		*SIDEGATE LOCK LH	Not Necessary	298.40 FL	*- FL
12	1		*SIDEGATE LOCK BRACKET LH	Repair	429.10 FL	*- FL
13	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
14	1		*FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*-FS
15	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
16	1		*70KM STICKER	Not Necessary	100.00 FS	*-FS
17	1		*TAILGATE 13 PAX STICKER	Not Necessary	100.00 FS	*-FS
18	1		*TAILGATE ADVERTISEMENT STICKER	Not Necessary	1,600.00 FS	*-FS
19	1		*SIDEGATE ADVERTISEMENT STICKER	Not Necessary	1,600.00 FS	*- FS
20	1		*SIDEGATE LH	Not Necessary	2,880.90 FL	*- FL
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	14,159.19	0.00
			- List Item Discount on	L Items 25.00/25.00% (S\$)	2,624.80	0.00
				Total Parts (S\$)	11,534.39	0.00
			Report was unsubmitted du	ring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO RNR REAR METAL DECK TO FACILITATE REPAIRS	New	1,800.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PART PANELS	rs & New	2,400.00	120.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED ARE	AS New	2,400.00	80.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
5	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	150.00	0.00
	G	ross Labour Cost (S\$)	7,050.00	200.00
	Report was unsubmitted	d during this print-out.		

< END OF ESTIMATES >