

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001537/AQY3E2

Date: 20/09/2022

REFERENCE

Insured/Claimant:	TER LI ANN	Policy No:	1900165810	
Date of Loss:	10/02/2022	Nature of Claim:	OD	Claim No: 9874161772SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP5396L		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK087858
Reg. Date:	30/09/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF54KA077002
Colour:	White	Odometer:	43431 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$158,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,778.00	15,712.24	22,065.76	58.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,532.00	3,502.00	9,030.00	72.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,310.00	19,214.24	31,095.76	61.81
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	49,510.00	18,414.24	31,095.76	62.81
+ GST 7.00/7.00% (S\$)	3,465.70	1,289.00	2,176.70	62.81
Nett Amount (S\$)	52,975.70	19,703.24	33,272.46	62.81

INSPECTION

Date of Assignment:	17/02/2022		
Date Inspected:	16/02/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,787.00 FS	*1,429.60 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	425.00 FS	*- FS
3	2	*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1	*FRONT BUMPER GRILLE-CENTER	Cracked	219.00 FS	*174.80 FS
5	1	*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	254.00 FS	*- FS
6	1	*FRONT BUMPER SPOILER	Repair	599.00 FS	*- FS
7	2	*FRONT BUMPER AIR GUIDE-LH/RH	Not Necessary	144.00 FS	*- FS
8	1	*RADIATOR GRILLE	Cracked	2,576.00 FS	*2,060.80 FS
9	1	*FRONT PARKING AID SENSOR SUPPORT-LH/RH	O/s Damaged	116.00 FS	*45.76 FS
10	1	*RADIATOR GRILLE COVER-UPPER	Not Necessary	209.00 FS	*- FS
11	1	*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	N/s Cracked	1,058.00 FS	*423.20 FS
12	1	*FRONT BUMPER FOAM FILLER PIECE	Cracked	139.00 FS	*110.80 FS
13	1	*FRONT BUMPER REINFORCEMENT BEAM	Dented	899.00 FS	*719.20 FS
14	2	*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	82.00 FS	*- FS
15	2	*FRONT BUMPER BRACKET-LH/RH	Not Necessary	508.00 FS	*- FS
16	1	*FRONT BUMPER TOP COVER	Cracked	143.00 FS	*114.00 FS
17	1	*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
18	1	*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
19	1	*FRONT BUMPER LOCK CARRIER BRACKET	Cracked	154.00 FS	*122.80 FS
20	2	*FRONT BUMPER LOCK CARRIER BRACKET SUPPORT-LH/RH	Not Necessary	64.00 FS	*- FS
21	4	*POP RIVET	Necessary	4.00 FS	*2.88 FS
22	2	*HORN-LH/RH	Not Necessary	273.00 FS	*- FS
23	2	*HORN SUPPORT-LH/RH	Not Necessary	66.00 FS	*- FS
24	2	*FRONT PARKING AID SENSOR-INNER	Missing	244.00 FS	*211.76 FS
25	4	*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
26	1	*FRONT BUMPER WIRING	Not Necessary	567.00 FS	*- FS
27	1	*BONNET	Buckled	3,491.00 FS	*2,792.80 FS
28	1	*BONNET ATTACHMENT PARTS	Not Necessary	128.00 FS	*- FS
29	3	*BONNET IMPACT PROTECTION-CENTER/LH/RH	Necessary	93.00 FS	*73.20 FS
30	2	*BONNET STRIKER-LH/RH	Not Necessary	112.00 FS	*- FS
31	2	*BONNET LOCK	Not Necessary	455.00 FS	*- FS
32	1	*BONNET BOWDEN CABLE-CENTER	Not Necessary	64.00 FS	*- FS
33	1	*BONNET RELEASE CABOER COVER	Not Necessary	11.00 FS	*- FS
34	1	*BONNET BOWDEN CABLE-OUTER	Not Necessary	64.00 FS	*- FS
35	1	*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
36	1	*HEADLIGHT-LH/RH	N/s Cracked	16,832.00 FS	*6,732.80 FS
37	2	*LIFT CYLINDER-LH/RH	Not Necessary	434.00 FS	*- FS
38	1	*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	100.00 FS	*- FS
39	1	*LOCK CARRIER	Not Necessary	1,127.00 FS	*- FS
40	2	*LOCK CARRIER SUPPORT-LH/RH	Cracked	85.00 FS	*33.84 FS
41	1	*CHARGED AIR COOLER	Dented	654.00 FS	*522.80 FS
42	1	*CHARGED AIR COOLER PRESSURE HOSE-RH	Not Necessary	413.00 FS	*- FS
43	1	*CHARGED AIR COOLER PRESSURE PIPE	Not Necessary	496.00 FS	*- FS
44	1	*A/C CONDENSER	Not Necessary	683.00 FS	*- FS
45	1	*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
46	1	*RADIATOR	Not Necessary	1,010.00 FS	*- FS
47	6	*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
48	2	*RADIATOR AIR GUIDE OUTER-LH/RH	Not Necessary	72.00 FS	*- FS
49	2	*RADIATOR AIR GUIDE INNER-LH/RH	Not Necessary	38.00 FS	*- FS
50	1	*RADIATOR AIR GUIDE UPPER	Not Necessary	19.00 FS	*- FS
51	1	*RADIATOR AIR GUIDE LOWER	Not Necessary	25.00 FS	*- FS
52	1	*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
53	1	*SUNDRIES	Necessary	350.00 FS	*45.84 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 37,778.00 15,712.24

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR.HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER.CHARGED AIR COOLER AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.VACUUM AND REGAS	New	1,700.00	480.00
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM.TO REMOVE REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR	New	560.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER.BONNET AND BOTH HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,800.00	1,000.00
6	TO RESPRAY FRONT BUMPER,BONNET AND BOTH FRONT DOORS	New	4,000.00	1,100.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			12,532.00	3,502.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >