

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22001538/AQY3N2**Date:** 27/06/2022**REFERENCE**

Insured/Claimant:	TAN SAIK HUAT	Policy No:	7210081540	
Date of Loss:	12/02/2022	Nature of Claim:	OD	Claim No: 4189232379SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNB296L</b>		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	DEM032018
Reg. Date:	28/07/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF44MN012721
Colour:	Blue	Odometer:	8228 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$163,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	27,517.00	15,209.84	12,307.16	44.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,232.00	4,282.00	8,950.00	67.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>40,749.00</b>	<b>19,491.84</b>	<b>21,257.16</b>	<b>52.17</b>
<b>- Excess (S\$)</b>	550.00	550.00	0.00	0.00
<b>(S\$)</b>	40,199.00	18,941.84	21,257.16	52.88
<b>+ GST 7.00/7.00% (S\$)</b>	2,813.93	1,325.93	1,488.00	52.88
<b>Nett Amount (S\$)</b>	<b>43,012.93</b>	<b>20,267.77</b>	<b>22,745.16</b>	<b>52.88</b>

**INSPECTION**

Date of Assignment:	17/02/2022		
Date Inspected:	16/02/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	393.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Cracked	219.00 FS	*174.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	293.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE-LH	Not Necessary	51.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT-UPPER CENTER	Cracked	293.00 FS	*234.00 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	151.00 FS	*- FS
9	1		*FRONT BUMPER TRIM-LH	Not Necessary	54.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	1,754.00 FS	*1,403.20 FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	212.00 FS	*169.20 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	899.00 FS	*719.20 FS
13	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	82.00 FS	*- FS
14	1		*FRONT BUMPER BRACKET LH	Bent	254.00 FS	*203.20 FS
15	1		*FRONT BUMPER TOP COVER	Deformed	143.00 FS	*114.00 FS
16	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
17	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
18	1		*FRONT BUMPER LOCK CARRIER BRACKET	Cracked	154.00 FS	*122.80 FS
19	2		*FRONT BUMPER SUPPORT-LH/RH	Damaged	64.00 FS	*51.04 FS
20	4		*POP RIVET	Necessary	4.00 FS	*2.88 FS
21	1		*HORN-LH	Not Necessary	134.00 FS	*- FS
22	1		*HORN SUPPORT-LH	Not Necessary	33.00 FS	*- FS
23	3		*FRONT PARKING AID SENSOR-INNER/OUTER	Not Necessary	488.00 FS	*- FS
24	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
25	1		*FRONT BUMPER WIRING SET	Not Necessary	642.00 FS	*- FS
26	1		*BONNET	Dented	3,425.00 FS	*2,740.00 FS
27	1		*BONNET ATTACHMENT PARTS	Not Necessary	431.00 FS	*- FS
28	2		*BONNET HINGE-LH/RH	Not Necessary	680.00 FS	*- FS
29	3		*BONNET IMPACT PROTECTION-CENTER/LH/RH	Necessary	93.00 FS	*73.20 FS
30	1		*HEADLAMPS COVER-LH	Not Necessary	49.00 FS	*- FS
31	1		*BONNET STRIKER-LH	Not Necessary	56.00 FS	*- FS
32	1		*BONNET LOCK	Not Necessary	228.00 FS	*- FS
33	1		*BONNET BOWDEN CABLE-CENTER	Not Necessary	64.00 FS	*- FS
34	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
35	1		*BONNET BOWDEN CABLE-OUTER	Not Necessary	64.00 FS	*- FS
36	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
37	1		*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS
38	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	256.00 FS	*- FS
39	1		*FRONT WHEEL SPOILER-LH	Not Necessary	82.00 FS	*- FS
40	1		*FRONT WHEEL SPOILER LOWER-LH	Not Necessary	39.00 FS	*- FS
41	1		*HEADLIGHT-LH	Cut	8,172.00 FS	*6,537.60 FS
42	1		*LIFT CYLINDER-LH	Not Necessary	231.00 FS	*- FS
43	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
44	1		*LOCK CARRIER	Not Necessary	1,127.00 FS	*- FS
45	1		*LOCK CARRIER SUPPORT-LH	Not Necessary	43.00 FS	*- FS
46	1		*A/C CONDENSER	Not Necessary	683.00 FS	*- FS
47	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
48	1		*CHARGED AIR COOLER	Dented	654.00 FS	*522.80 FS
49	1		*CHARGED AIR COOLER PRESSURE HOSE-LH	Not Necessary	496.00 FS	*- FS
50	1		*RADIATOR	Not Necessary	699.00 FS	*- FS
51	6		*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
52	1		*RADIATOR AIR GUIDE OUTER LH/RH	N/s Deformed	102.00 FS	*40.08 FS
53	1		*RADIATOR AIR GUIDE INNER LH/RH	N/s Deformed	38.00 FS	*14.64 FS
54	1		*RADIATOR AIR GUIDE UPPER	Not Necessary	19.00 FS	*- FS
55	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SUNDRIES	Necessary	400.00 FS	*90.24 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					27,517.00	15,209.84

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER,CHARGED AIR COOLER AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT	New	1,400.00	480.00
4	TO CARRY OUT PRESURISE.VACUUM AND REGAS FOR R1234	New	1,200.00	0.00
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	0.00
6	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND LHS HEADLIGHT.TO REPAIR LHS FRONT FENDER.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,550.00	1,000.00
7	TO RESPRAY FRONT BUMPER,BONNET HINGES LHS FRONT FENDER AND LHS FRONT DOOR	New	4,000.00	1,100.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	TO DISLODGE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF FRONT REINFORCEMENT BEAM BRACKET (Supplementary)	New	780.00	780.00
<b>Gross Labour Cost (S\$)</b>			<b>13,232.00</b>	<b>4,282.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >