

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22001541/UPA3Q2**Date:** 04/01/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MPC0001472-02
Claimant Vehicle No : SKW7070A **Insured Vehicle No :** SFW2323M
 Date of Loss: 16/02/2022 Nature of Claim: TP Claim No: MPC2022D0000754

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW7070A**
 Make & Model: AUDI A6, 2.0 TFSI MU (A) Engine No: CDN416505
 Reg. Date: 26/03/2015 (Man. Year: 2014) Chassis No: WAUZZZ4GXEN198862
 Colour: Black Odometer: 107395 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19 Rear Tyre Size: 245/40 R19
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,128.00	13,343.90	12,784.10	48.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	2,370.00	1,490.00	38.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,988.00	15,713.90	14,274.10	47.60
Approved Total (Overridden) (S\$)		12,500.00		
Nett Amount (S\$)	29,988.00	12,500.00	17,488.00	58.32
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		13,227.45		

INSPECTION

Date of Assignment: 17/02/2022
 Date Inspected: 17/02/2022 Inspected At: Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Sep 2022)
Parts:	143	AUDI A6 2.0 TFSI MU (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW7070A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR O/S	Not Necessary	3,280.00 F	*- FL
2	1		*REAR FENDER O/S	Badly Dented	7,500.00 F	*4,870.00 FL
3	1		*REAR FENDER GLASS O/S	Necessary	880.00 F	*348.00 FL
4	1		*REAR FENDER INNER TRIM O/S	Not Necessary	428.00 F	*- FL
5	1		*REAR FENDER INNER PANEL O/S	Repair	1,100.00 F	*- FL
6	1		*REAR FENDER UNDER CLOTH O/S	Deformed / Torn	381.00 F	*355.00 FL
7	1		*SET REAR FENDER UNDER CLOTH CLIPS O/S	Necessary	50.00 F	*50.00 FL
8	1		*TAILLAMP O/S	Cracked	1,050.00 F	*1,050.00 FL
9	1		*TAILLAMP HOUSING PANEL O/S	Dented	845.00 F	*845.00 FL
10	1		*REAR WINDSCREEN MOULDING	Necessary	118.00 F	*118.00 FL
11	1		*REAR BUMPER	Distorted	2,400.00 F	*2,400.00 FL
12	1		*REAR BUMPER SIDE HOLDER O/S	Cracked	115.00 F	*115.00 FL
13	1		*REAR BUMPER SIDE TOP BRACKET O/S	Cracked	90.00 F	*90.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
15	1		*REAR BUMPER PDC SENSOR O/S	Serviceable	188.00 F	*- FL
16	1		*REAR AIR VENT O/S	Cracked	112.00 F	*85.00 FL
17	1		*REAR SHOCK ABSORBER O/S	Twisted	826.00 F	*563.00 FL
18	1		*REAR WHEEL HUB BEARING O/S	Damaged	1,450.00 F	*723.00 FL
19	1		*REAR KNUCKLE ARM O/S	Warped	1,550.00 F	*1,100.00 FL
20	1		*REAR LOWER ARM O/S	Serviceable	915.00 F	*- FL
21	1		*REAR SPORT RIM 19 INCH O/S	Warped	2,100.00 F	*1,200.00 FL
22	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
23	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
24	1		*REAR TYRE O/S	Serviceable	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,128.00	14,042.00
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	698.10

Total Parts (\$\$)	26,128.00	13,343.90
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REPLACED REAR FENDER GLASS O/S	New	100.00	60.00
5	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REPLACED REAR UNER CARRIAGE	New	280.00	150.00
7	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
8	TO DISMANTLE & REFIX FUEL TANK	New	100.00	60.00
9	TO SPRAY RUST PROOFING	New	100.00	50.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	900.00
11	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (S\$)			3,860.00	2,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >