

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001546/VQY3N2**Date:** 29/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00081392100		
Claimant Vehicle No :	SMD7216Z	Insured Vehicle No :	SMU515S		
Date of Loss:	15/02/2022	Nature of Claim:	TP	Claim No:	SNM22D201198/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD7216Z		
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Engine No:	2NRX356932
Reg. Date:	31/08/2018 (Man. Year: 2018)	Chassis No:	MHFZ28H3300056260
Colour:	Grey	Odometer:	64282 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,874.76	921.42	8,953.34	90.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	860.00	3,110.00	78.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,844.76	1,781.42	12,063.34	87.13
Approved Total (Overridden) (\$\$)		1,450.00		
(\$\$)	13,844.76	1,450.00	12,394.76	89.53
+ GST 7.00/7.00% (\$\$)	969.13	101.50	867.63	89.53
Nett Amount (\$\$)	14,813.89	1,551.50	13,262.39	89.53

INSPECTION

Date of Assignment:	18/02/2022	
Date Inspected:	03/03/2022 Inspected At:	Abwin Service Pte Ltd (HQ) 17 Kaki Bukit Road 4, Bartley Biz Centre #01-58/59/60/61/62 Singapore 417809
Estimated Period of Repair:	3.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Mar 2022)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD7216Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Repair	1,117.85 F	*- FL
2	1		*TAIL GATE LOCK	Serviceable	276.27 F	*- FL
3	1		*TAIL GATE CATCH	Serviceable	45.00 F	*- FL
4	1		*TAIL GATE INNER TRIM	Serviceable	179.49 F	*- FL
5	1		*TAIL GATE INNER TRIM HANDLE	Serviceable	68.33 F	*- FL
6	1		*TAIL GATE HINGE RH	Serviceable	55.62 F	*- FL
7	1		*TAIL GATE HINGE LH	Serviceable	55.62 F	*- FL
8	1		*TAIL GATE DAMPER RH	Serviceable	239.70 F	*- FL
9	1		*TAIL GATE DAMPER LH	Serviceable	239.70 F	*- FL
10	1		*TAIL GATE EMBLEM LOGO TOYOTA	Necessary	79.00 F	*79.00 FL
11	1		*TAIL GATE EMBLEM SIENTA	Necessary	87.80 F	*87.80 FL
12	1		*TAIL GATE OUTER CHROME MOULDING	Serviceable	236.23 F	*- FL
13	1		*TAIL GATE WEATHER STRIP	Serviceable	255.20 F	*- FL
14	1		*TAIL LAMP RH	Serviceable	358.70 F	*- FL
15	1		*TAIL LAMP LH	Serviceable	358.70 F	*- FL
16	1		*TAIL GATE LAMP RH	Serviceable	199.50 F	*- FL
17	1		*TAIL GATE LAMP LH	Serviceable	199.50 F	*- FL
18	1		*REAR CORNER PANEL RH	Dented	720.50 F	*310.00 FL
19	1		*REAR CORNER PANEL LH	Serviceable	720.50 F	*- FL
20	1		*REAR BUMPER	Cut	337.50 F	*337.50 FL
21	1		*REAR BUMPER DIFUSSER	Serviceable	198.90 F	*- FL
22	1		*REAR BUMPER REFLECTOR RH	Scratched	67.60 F	*67.60 FL
23	1		*REAR BUMPER REFLECTOR LH	Serviceable	67.60 F	*- FL
24	1		*REAR BUMPER CENTRE REFLECTOR	Serviceable	62.50 F	*- FL
25	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	87.60 F	*- FL
26	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	87.60 F	*- FL
27	1		*REAR END PANEL OUTER	Repair	359.22 F	*- FL
28	1		*REAR END PANEL INNER	Repair	595.03 F	*- FL
29	1		*REAR END PANEL TOP GARNISH	Serviceable	158.00 F	*- FL
30	1		*FLOOR PANEL	Repair	950.00 F	*- FL
31	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
32	1		*TAILGATE SEALANT	Not Necessary	50.00 FS	*- FS
33	1		*WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
34	2		*REAR BUMPER SENSOR	Cut	720.00 FS	*200.00 FS
35	1		*REVERSE CAMERA	Serviceable	380.00 FS	*- FS
36	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
37	1		*REAR NUMBER PLATE WITH BRACKET	Serviceable	60.00 FS	*- FS
38	10		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,874.76	1,141.90
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	220.48
Total Parts (\$\$)	9,874.76	921.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	New	1,600.00	400.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,600.00	400.00
3	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
4	TO APPLY TUFF COAT ON AFFECTED AREAS	New	150.00	30.00
5	TO DISMANTLE,REPLACE AND/OR REPAIR TAILGATE COMPONENTS	New	150.00	0.00
6	TO DISMANTLE,REPLACE AND/OR REPAIR REVERSE CAMERA & TESTING	New	150.00	30.00
7	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	New	200.00	0.00
Gross Labour Cost (\$\$)			3,970.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >