6/3/22, 4:30 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22001547/ETY3M4

03/06/2022 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00065052101

**Claimant Vehicle** 

SML3614S

Insured Vehicle No:

SJP6220P

No:

Date of Loss: 30/12/2021 Nature of Claim: TP

Claim

Engine No:

Chassis No:

Odometer:

SNM22D200007/C02/LEEPG

JHMRU1810GX200289

Yes

L15B4530288

224679 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SML3614S Reg No:

Make & Model: HONDA HR-V, 1.5 DX CVT (A)

Reg. Date: 07/10/2016 (Man. Year: 2016)

Colour: Beige

**Engine Capacity:** 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Rear Left Side: Goodvear 5 mm Goodvear 5 mm Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS         | Repairer's | Adjuster's | Difference | Diff % |
|------------------------|------------|------------|------------|--------|
| Parts                  | 3,148.00   | 1,584.28   | 1,563.72   | 49.67  |
| Miscellaneous Items    | 0.00       | 0.00       | 0.00       |        |
| Labour                 | 5,340.00   | 1,240.00   | 4,100.00   | 76.78  |
| Paintwork Labour       | 0.00       | 0.00       | 0.00       |        |
| Towing                 | 0.00       | 0.00       | 0.00       |        |
| Gross Total (S\$)      | 8,488.00   | 2,824.28   | 5,663.72   | 66.73  |
| + GST 7.00/7.00% (S\$) | 594.16     | 197.70     | 396.46     | 66.73  |
| Nett Amount (S\$)      | 9,082.16   | 3,021.98   | 6,060.18   | 66.73  |

**INSPECTION** 

Date of Assignment: 17/02/2022

REPUBLIC AUTO PTE LTD (HQ)

Date Inspected: 13/04/2022 Inspected At: 209 PANDAN GARDENS

SINGAPORE 609339

Estimated Period of Repair: 4.0 days

DENISE TAY KWEE CHENG Adjuster: **CHEN TSUE YEE** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/3/22, 4:30 PM Adjuster Report

### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 03 Jun 2022)

Parts: N/A HONDA HR-V 1.5 DX CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SML3614S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

| No.   | Qty    | Part No.      | Particulars                | Condition                    | Repairer's | Amount     |
|-------|--------|---------------|----------------------------|------------------------------|------------|------------|
| 1     | 1      |               | *REAR BOOT PANEL           | Dented                       | 1,068.00 F | *912.60 FL |
| 2     | 1      |               | *REAR BUMPER               | Crushed                      | 829.00 F   | *829.00 FL |
| 3     | 1      |               | *HONDA PLATE               | Not Necessary                | 25.00 F    | *-FL       |
| 4     | 1      |               | *WINDSHIELD GLASS RR       | Not Necessary                | 980.00 F   | *- FL      |
| 5     | 1      |               | *EMBLEM I-VTEC             | Necessary                    | 35.00 FS   | *35.00 FS  |
| 6     | 1      |               | *EMBLEM HR-V               | Necessary                    | 35.00 FS   | *35.00 FS  |
| 7     | 1      |               | *WINDSHIELD GLASS MOUNTING | Necessary                    | 76.00 FS   | *76.00 FS  |
| 8     | 1      |               | *SUNDRIES                  | Necessary                    | 50.00 FS   | *20.00 FS  |
| 9     | 1      |               | *RUBBER W/SHLD DAM         | Necessary                    | 25.00 FS   | *25.00 FS  |
| 10    | 1      |               | *MOULDING ASSY L FRT DOOR  | Not Necessary                | 25.00 FS   | *-FS       |
| F=Fra | nchise | part. S=SpcNe | ett. L=ListItemDisc.       |                              |            |            |
|       |        |               |                            | Sub Total (S\$)              | 3,148.00   | 1,932.60   |
|       |        |               | - List Item Discount       | on L Items 0.00/20.00% (S\$) | 0.00       | 348.32     |
|       |        |               |                            | Total Parts (S\$)            | 3,148.00   | 1,584.28   |
|       |        |               | Report was unsubmitte      | d during this print-out.     |            |            |

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No         | Particulars  | Lab.Type      | Repairer's | Amount   |
|------------|--|---------------|------------|----------|
| <u>Lab</u> | our Items  |               |            |          |
| 1          | REPLACE REAR BUMPER, TAILGATE & AFFECTED AREA REPAIR ON END PANEL. (300 X 2) | New           | 2,560.00   | 600.00   |
| 2          | PAINT WORK ON REAR TAILGATE & END PANEL. (250 X 1)                           | New           | 1,650.00   | 250.00   |
| 3          | REMOVE & INSTALL REAR PARKING ASSISTS.                                       | New           | 150.00     | 40.00    |
| 4          | REMOVE & INSTALL REAR WINDSCREEN FOR FACILITATE REPAIR.                      | New           | 300.00     | 150.00   |
| 5          | TO APPLY WINDSCREEN SEALANT.   | New           | 100.00     | 50.00    |
| 6          | TO APPLY SEALANT ON AFFECTED AREA.   | New           | 80.00      | 30.00    |
| 7          | PERFORM RUST PREVENTION.   | New           | 80.00      | 0.00     |
| 8          | CHECK WIRING & CHASSIS ELECTRICAL SYSTEM.                                    | New           | 120.00     | 120.00   |
| 9          | TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM.                  | New           | 300.00     | 0.00     |
|            | Gross Labou  | ır Cost (S\$) | 5,340.00   | 1,240.00 |
|            | Report was unsubmitted during this   | print-out.    |            |          |

< END OF ESTIMATES >