10/27/22, 3:36 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22001549/ENY3Q2

**Date:** 27/10/2022

**REFERENCE** 

Handling Insurer: China Taiping Insurance (Singapore)

Pte. Ltd.

Policy No: DMCVSNW00012652201

**Claimant Vehicle** 

SMZ2653L

Insured Vehicle No :

YN3361T

Date of Loss:

No:

06/02/2022

Nature of Claim: TP

Claim No:

SNM22D201008/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMZ2653L

Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: Reg. Date: 19/04/2021 (Man. Year: 2021) Chassis No:

Odometer:

4J11DC4965 GF7W0701228

9241 km

Colour: White Engine Capacity: 1998 cc

Engine Capacity: 1999 Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS         | Repairer's | Adjuster's | Difference | Diff % |
|------------------------|------------|------------|------------|--------|
| Parts                  | 3,073.00   | 2,533.00   | 540.00     | 17.57  |
| Miscellaneous Items    | 0.00       | 0.00       | 0.00       |        |
| Labour                 | 2,860.00   | 1,590.00   | 1,270.00   | 44.41  |
| Paintwork Labour       | 0.00       | 0.00       | 0.00       |        |
| Towing                 | 0.00       | 0.00       | 0.00       |        |
| Gross Total (S\$)      | 5,933.00   | 4,123.00   | 1,810.00   | 30.51  |
| + GST 7.00/7.00% (S\$) | 415.31     | 288.61     | 126.70     | 30.51  |
| Nett Amount (S\$)      | 6,348.31   | 4,411.61   | 1,936.70   | 30.51  |

**INSPECTION** 

Date Inspected:

Date of Assignment: 13/06/2022

Cycle & Carriage Automotive Pte Ltd (Pandan

17/05/2022 Inspected At: Gardens)

209 Pandan Gardens Singapore 609339

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: HUEY YON

any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Oct 2022)

Parts: M1-SUV MITSUBISHI OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMZ2653L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

| Qty     | Part No.   | Particulars                  | Condition   | Repairer's  | Amount   |
|---------|--|------------------------------|---|---|--|
| 1       |  | *SUNDRIES                    | Necessary   | 50.00 FS  | *20.00 FS  |
| 1       |  | *FACE ,FR BUMPER             | Crushed   | 851.00 FS   | *851.00 FS   |
| 1       |  | *GRILLE ASSY ,RADIATOR       | Cracked   | 550.00 FS   | *550.00 FS   |
| 1       |  | *MARK ,THREE -DIA            | Necessary   | 72.00 FS  | *72.00 FS  |
| 1       |  | *EXTENSION ,FR BUMPER        | Cut   | 509.00 FS   | *509.00 FS   |
| 1       |  | *COVER ,FR BUMPER            | Cut   | 361.00 FS   | *361.00 FS   |
| 1       |  | *REINFORCEMENT ,FR BUMPER    | Not Necessary   | 510.00 FS   | *-FS   |
| 1       |  | *FRT NUMBER PLATE WITH FRAME | Cut   | 50.00 FS  | *50.00 FS  |
| 10      |  | *CLIP ,RR BUMPER             | Necessary   | 30.00 FS  | *30.00 FS  |
| 20      |  | *CLIP ,ENG ROOM COVER        | Necessary   | 40.00 FS  | *40.00 FS  |
| 10      |  | *RIVET ,FR BUMPER            | Necessary   | 50.00 FS  | *50.00 FS  |
| anchise | part. S=SpcNe  | ett.                         | _   |   |  |
|         |  |                              | Total Parts (S\$)   | 3,073.00  | 2,533.00   |
|         | 1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>20 | 20                           | 1 *SUNDRIES 1 *FACE ,FR BUMPER 1 *GRILLE ASSY ,RADIATOR 1 *MARK ,THREE -DIA 1 *EXTENSION ,FR BUMPER 1 *COVER ,FR BUMPER 1 *REINFORCEMENT ,FR BUMPER 1 *FRT NUMBER PLATE WITH FRAME 10 *CLIP ,RR BUMPER 20 *CLIP ,ENG ROOM COVER | 1 *SUNDRIES Necessary 1 *FACE ,FR BUMPER Crushed 1 *GRILLE ASSY ,RADIATOR Cracked 1 *MARK ,THREE -DIA Necessary 1 *EXTENSION ,FR BUMPER Cut 1 *COVER ,FR BUMPER Cut 1 *REINFORCEMENT ,FR BUMPER Not Necessary 1 *FRT NUMBER PLATE WITH FRAME Cut 10 *CLIP ,RR BUMPER Necessary 20 *CLIP ,ENG ROOM COVER Necessary 10 *RIVET ,FR BUMPER Necessary 10 *RIVET ,FR BUMPER Necessary | 1         *SUNDRIES         Necessary         50.00 FS           1         *FACE ,FR BUMPER         Crushed         851.00 FS           1         *GRILLE ASSY ,RADIATOR         Cracked         550.00 FS           1         *MARK ,THREE -DIA         Necessary         72.00 FS           1         *EXTENSION ,FR BUMPER         Cut         509.00 FS           1         *COVER ,FR BUMPER         Cut         361.00 FS           1         *REINFORCEMENT ,FR BUMPER         Not Necessary         510.00 FS           1         *FRT NUMBER PLATE WITH FRAME         Cut         50.00 FS           10         *CLIP ,RR BUMPER         Necessary         30.00 FS           20         *CLIP ,ENG ROOM COVER         Necessary         40.00 FS           10         *RIVET ,FR BUMPER         Necessary         50.00 FS |

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No  | Particulars  | Lab.Type     | Repairer's | Amount   |
|-----|--|--------------|------------|----------|
| Lab | our Items  |              |            |          |
| 1   | REPLACE FRT BUMPER & AFFECTED AREA                         | New          | 1,280.00   | 640.00   |
| 2   | PAINT WORK ON FRT BUMPER PANEL                             | New          | 1,100.00   | 550.00   |
| 3   | PERFORM RUST PREVENTION                                    | New          | 80.00      | 0.00     |
| 4   | CHECK WIRING & CHASSIS ELECTRICAL SYSTEM                   | New          | 120.00     | 120.00   |
| 5   | TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRICAL CONTROL SYSTEM | New          | 280.00     | 280.00   |
|     | Gross Labour Cost (S\$)                                    |              | 2,860.00   | 1,590.00 |
|     | Report was unsubmitted during this                         | s print-out. |            |          |

< END OF ESTIMATES >