



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 9606G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT	DENTED	1,853.60	1,635.00
1	REAR BOOT LOGO	NECESSARY	72.20	72.20
1	REAR BOOT 'ESTIMA' EMBLEM	NECESSARY	75.70	75.70
1	RT REAR BOOT INNER STOPPER	NOT NECESSARY	29.80	-
1	REAR WINDSCREEN MOULDING	NECESSARY	110.60	110.60
1	RT REAR BOOT REFLECTOR	BROKEN	784.90	784.90
1	RT REAR TAIL LIGHT	BROKEN	667.00	667.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	622.10	-
1	SET REAR BUMPER CLIPS	NOT NECESSARY	66.00	-
2	REAR BUMPER SIDE RETAINERS @\$67.70	NOT NECESSARY	135.40	-
2	REAR BUMPER SENSORS @\$310.90	NOT NECESSARY	621.80	-
	LESS 25% DISCOUNT		-1,259.78	-836.35
			3,779.32	2,509.05
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	42.00	30.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	55.00	40.00
			97.00	70.00
<u>LABOUR</u>				
	TO KNOCK, STRAIGHTEN REAR SUPPORT PANEL, REAR INNER PANEL, REAR LOWER PANEL, REAR SIDE PANEL, RT REAR FENDER, RT REAR FENDER INNER PANEL, RT REAR FLOOR BOARD, RENEW REAR BOOT, REAR REFLECTOR, REAR LIGHTS, REAR BUMPER AND ASSEMBLY. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		1,200.00	500.00
	TO RESPRAY DAMAGED PARTS.		1,200.00	600.00
	TO REMOVE, REPLACE REAR WINDSCREEN.		180.00	120.00
	TO REMOVE REAR GARNISHES, CARPETS, UPHOLSTERY, REAR SEATS, SIDE COVERS TO FACILITATE REPAIRS AND ASSEMBLY.		280.00	50.00
	TO REMOVE, REPLACE, TRANSFER REAR BOOT INNER LOCK, OUTER LOCK, INNER MOTORS, RUBBERS, MOULDINGS AND ASSEMBLY.		150.00	50.00

Report Ref No. CS/FCI22001550/Eqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESEAL JOINTS, REINSULATE, ANTI RUST PANELS AND ASSEMBLY.		120.00	30.00
			3,130.00	1,350.00
GRAND TOTAL			7,006.32	3,929.05
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,150.00

Report Ref No. CS/FCI22001550/Eqf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.