

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001552/AGA3Q2**Date:** 19/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210014828-01
Claimant Vehicle No :	PC3493K	Insured Vehicle No :	SMY1320J
Date of Loss:	12/02/2022	Nature of Claim:	TP
		Claim No:	4833607334SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC3493K		
Make & Model:	TOYOTA HIACE, 3.0 D HIGH ROOF COMMUTER TURBO (A)	Engine No:	1KD2411268
Reg. Date:	22/06/2015 (Man. Year: 2014)	Chassis No:	JTFST22P300020188
Colour:	Silver	Odometer:	253587 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	OHTSU 6 mm	Rear Left Side:	OHTSU 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	OHTSU 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,733.32	636.30	3,097.02	82.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	890.00	3,170.00	78.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,793.32	1,526.30	6,267.02	80.42
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	7,793.32	1,200.00	6,593.32	84.60
+ Loss of Use (4.0 x S\$150.00/day) (S\$)		600.00		
(S\$)		1,800.00		
Liabe Amount (50.00%) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		902.00		
Global Sum Settlement (S\$)		800.00		

INSPECTION

Date of Assignment:	17/02/2022	
Date Inspected:	17/02/2022	Inspected At: Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	431.60 FL	*431.60 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Necessary	67.20 FL	*67.20 FL
3	1		*RH REAR FENDER	Repair	2,598.20 FL	*- FL
4	1		*RH REAR FENDER AIR VENT	Not Necessary	53.60 FL	*- FL
5	1		*RH REAR TAILLAMP	Cut	297.60 FL	*297.60 FL
6	1		*RH REAR TAILLAMP LOWER APRON PANEL	Repair	125.60 FL	*- FL
7	1		*RH REAR TAILLAMP PANEL	Not Necessary	485.30 FL	*- FL
8	1		*SET WHEEL CAP	Not Necessary	380.00 FS	*- FS
9	1		*RH REAR FENDER GLASS SEALANT	Not Necessary	180.00 FS	*- FS
10	2		*RH REAR TAILLAMP CLIPS	Necessary	9.00 FS	*9.00 FS
11	1		*RH REAR TAILLAMP PANEL SEALANT	Not Necessary	60.00 FS	*- FS
12	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,748.10	835.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,014.78	199.10
Total Parts (\$\$)	3,733.32	636.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	2,000.00	400.00
2	LABOUR FOR SPRAY PAINTING	New	1,200.00	400.00
3	WIRING CHECK	New	80.00	30.00
4	LABOUR FOR REMOVE & REFIX RH REAR FENDER GLASS	New	180.00	0.00
5	LABOUR FOR REMOVE & REFIX RH UPHOLSTERY ROOF LINING	New	300.00	0.00
6	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS	New	300.00	60.00
Gross Labour Cost (\$\$)			4,060.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >