



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 5446M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TAILGATE BADGE -LOGO (CONSISTENT)	NOT NECESSARY	62.80	-
1	TAILGATE 'HYBRID' EMBLEM (CONSISTENT)	NECESSARY	78.30	78.30
1	TAILGATE 'VEZEL' EMBLEM (CONSISTENT)	NECESSARY	67.50	67.50
1	REAR BUMPER (CONSISTENT)	DEFORMED	957.20	762.00
1	SET REAR BUMPER REFLECTORS (CONSISTENT)	CUT	89.80	89.80
	LESS 25% DISCOUNT		-	-249.40
			1,255.60	748.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REVERSE SENSOR (SN)(CONSISTENT)	SHORTED	250.00	200.00
			250.00	200.00
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES TO REPAIR ,PANEL BEAT AND STRAIGHTEN DAMAGED PARTS AND REPLACE THE ABOVE MENTIONED PARTS.		300.00	220.00
	TO REPLACE REVERSE SENSOR AND CHECK WIRING FUNCTIONS.		70.00	50.00
	TO PUTTY ,APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS .		500.00	420.00
			870.00	690.00
<b>GRAND TOTAL</b>			<b>2,375.60</b>	<b>1,638.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,300.00</b>

Report Ref No. CC4/ASM22001555/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.