

CO RTDEL ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA5758P

DATE 29/01/2022

MAKE REG 12.05.2016

CHIANG /NTUC

MODEL HYU- I40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
				\$1,388.00
1	HEADLAMP LH			\$663.00
1	FENDER LH			\$174.90
1	FENDER SHIELD LH			\$14.30
1	FRONT BUMPER SIDE RH /LH			\$24.60
1	FRONT BUMPER BRACKET LH/RH			\$187.20
1	FRONT BUMPER GRILLE LH			\$1,052.20
1	FRONT BUMPER ASSY			\$907.40
1	HEADLAMP SUPPORT PANEL			\$715.00
1	LH ROCKER GARNISH			\$214.20
1	WHEEL HUB COVER			
	SUB TOTAL			\$5,340.80
	20.00%			\$1,068.16
	DISCOUNTED TOTAL			\$4,272.64
1	FRT TYRE RH			\$216.00
1	FRT DOOR LOGO STICKER			\$75.00
1	FRT DOOR COMFORTDELGRO STICKER			\$75.00
				\$329.40
	Labour Charge			
	Panel Beating			\$700.00
	Spray Painting Charge			\$1,000.00
	Check wiring			\$60.00
	Tuff kote			\$60.00
	TOTAL LABOUR			\$1,820.00
	ESTIMATE TOTAL			\$6,422.04
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

7. XSVC
 7. DT
 7. XSVC
 - nec
 - nec
 XSVC
 DT
 7. XSVC
 XSVC
 DT

XSVC
 nec
 nec

S60
 S00
 20
 20

z

Then
 82235769
 4/2/22 1600
 L/S after repair photo
 wp 3clays

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: