

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



NTUC INCOME INSURANCE CO-OPERATIVE LTD Rei				Ref: NS/INC22001558/Vty3n2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556				09-03-2022 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJG 8062M	Veh. Ir	nspected	SHC 7144L	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1163575-001	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	04/02/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU087449	Colou		YELLOW	
	Odometer	567113	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	206/60 R16	WEST	LAKE	5 mm	
	L/H Front Tyre	206/60 R16	WEST	LAKE	5 mm	
	R/H Rear Tyre	206/60 R16	WEST		5 mm	
	L/H Rear Tyre	206/60 R16	WEST	_AKE	5 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	03/02/2022	Inspec	tion Date	04/02/2022	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					