



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4377G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER BRACKET RH	NECESSARY	24.60	24.60
1	FRONT BUMPER TOP BRACKET RH	NECESSARY	22.40	22.40
1	FRONT BUMPER	DENTED	1,052.20	1,052.20
1	FRONT BUMPER GRILLE/RH	SERVICEABLE	93.45	-
1	FRONT FENDER RH	DENTED	663.00	663.00
1	FRONT FENDER SHIELD RH	SERVICEABLE	174.90	-
1	HEAD LAMP SUPPORT PANEL	SERVICEABLE	907.40	-
1	HEAD LAMP ASSY RH	SERVICEABLE	1,388.00	-
10	BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-869.59	-356.84
			3,478.36	1,427.36
LABOUR				
	PANEL BEATING.		600.00	560.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.		60.00	20.00
	CHECK LIGHTING.		60.00	20.00
			1,320.00	1,100.00
GRAND TOTAL			4,798.36	2,527.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,000.00

Report Ref No. NS/INC22001559/Vqy3n2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.