

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Chlns No: **MT/1163440-001**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHB43770 Yr Rogn: 2012 117  
 Type: M.Car / M.Cycle / Bus / Van / Lorry /  Prime Mover /  
 Truck / Trailer or  
 Make: Hyundai i40 c.c. 1685  
 Colour: Blue A/C:  Insured / Std / NI / NA  
 Sp. Reading: 515004 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KMHLB Ulumt/4099990  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  Good / Jammed / Leaked / Burnt or  
 Brake:  Good / Jammed / Leaked / Burnt or  
 Modi:  Nil /  RIm / STD A/RIm or  
 Tyre Size: F: 206/60R16  
 R: 206/60R16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Westlake  
 Front R/Bal: 5 mm Rear R/Bal: 5 mm  
 L/Bal: 5 mm L/Bal: 5 mm  
 D.O.A. 3/2/22 D.O.I. 4/2/22 1645  
 Survey held at CDGE  
 Des. of Damages:  Front / Rear / O/S / N/S / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	NO OIA given
	Thevan finalised LS \$2000, 3 days. (Red \$2798.36, 58%)

Date/Time, File Pass to?  : Prel. Report  
 : Final Report  
 Date/Time, File Return to? 3

Days Of Repair: 3  
 Resurvey No. of Trlp: 1

Survey Fee:	
Transportation:	
S + RS: \$	
Finalis	
Others	
Total	

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Wash and (\$ \_\_\_\_\_)

Request Fee/ins: TP  
 Limit: 2000

Team: ARC Repair TP(CLSO)1

## JOB CARD

Sales Order: 4170263

JC NO 305503590

CUSTOMER  
 IR/MS COMFORT TRANSPORTATION PTE LTD  
 CUSTOMER NO 7010045  
 ADDRESS 383 SIN MING DRIVE  
 Singapore SINGAPORE 575717  
 TEL (R) 65508755 (O)  
 (P)


REGN NO SHB4377G	MILEAGE
MAKE HYUNDAI	FUEL E 1/2 F
MODEL I-40	DATE/TIME IN 03.02.2022 23:30
YR OF MANU 20.12.2017	TARGET DATE
CHASSIS CODE KMFILB41UMHU099990	COMPLETION DATE/TIME

DISCOUNT CARD NO

### JOB DESCRIPTION

Accident Date: 03.02.2022  
 NATURE: 3P 03.02.22

S/NO                      LABOR CODE                      DESCRIPTION



CHECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

No.:  
 No.:  
 Vehicle No.: SHB4377G                      CHIANG

Vehicle No.: SHB4377G

Signature/Date

Name of Service Advisor

Date

To be kept by Security Guard

To be kept by Service Reception/Collection

COMFORTDELGRO PTE LTD

REPAIR ESTIMATE\*

03/02/22

VEHICLE NO SHB4377G

MAKE REG. 20.12.2017

MODEL I-40

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
				\$24.60	NAC
1	FRONT BUMPER BRACKET RH			\$22.40	NAC
1	FRONT BUMPER TOP BRACKET RH			\$1,052.20	DT
1	FRONT BUMPER			\$93.45	XSVc
1	FRONT BUMPER GRILLE / RH			\$663.00	DT
1	FRONT FENDER RH			\$174.90	XSVc
1	FRONT FENDER SHIELD RH			\$907.40	n.
1	HEAD LAMP SUPPORT PANEL			\$1,388.00	n.
1	HEAD LAMP ASSY RH		\$2.20	\$22.00	NAC
10	BUMPER CLIPS				
	<b>SUB TOTAL</b>			<b>\$4,347.95</b>	
	<b>LESS 20%</b>			<b>\$869.59</b>	
				<b>\$3,478.36</b>	
	<b>Labour Charge</b>			<b>\$600.00</b>	S60
	Panel Beating			\$600.00	S00
	Spray Painting Charge			\$60.00	20
	Tuff Kote			\$60.00	20
	Check Lighting				
	<b>TOTAL LABOUR</b>			<b>\$1,320.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$4,798.36</b>	

Thevan  
 82235769  
 4/12/22  
 1645  
 LIS after repair photo  
 3days wp

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer