

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001560/AEA3Q2**Date:** 16/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900117863
Claimant Vehicle No :	SMP9028Z	Insured Vehicle No :	SMM6732J
Date of Loss:	07/02/2022	Nature of Claim:	TP
		Claim No:	4838053219SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP9028Z	Engine No:	A2183339JR5X0041
Make & Model:	OPEL ASTRA ST, 1.6 D TURBO DIESEL (A)	Chassis No:	W0VBD8EG2K8031343
Reg. Date:	22/10/2019 (Man. Year: 2019)	Odometer:	41653 km
Colour:	Green		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,973.10	10,237.50	7,735.60	43.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,455.00	6,160.00	7,295.00	54.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,428.10	16,397.50	15,030.60	47.83
Approved Total (Overridden) (S\$)		13,100.00		
(S\$)	31,428.10	13,100.00	18,328.10	58.32
+ GST 7.00/7.00% (S\$)	2,199.97	917.00	1,282.97	58.32
Nett Amount (S\$)	33,628.07	14,017.00	19,611.07	58.32
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		14,719.00		

INSPECTION

Date of Assignment:	16/02/2022		
Date Inspected:	16/02/2022	Inspected At:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH WING MIRROR ASSY	Not Necessary	432.00 FL	*- FL
2	1		*RH WING MIRROR MOTOR	Not Necessary	191.00 FL	*- FL
3	1		*RH WING MIRROR COVER	Not Necessary	121.00 FL	*- FL
4	1		*RH WING MIRROR GLASS	Not Necessary	221.00 FL	*- FL
5	1		*RHF DOOR	Distorted	2,010.00 FL	*2,010.00 FL
6	1		*RHF DOOR BLACK STICKER	Necessary	117.00 FL	*117.00 FL
7	1		*RHF DOOR OUTER GLASS RUN	Not Necessary	83.00 FL	*- FL
8	1		*RHF DOOR CHROME MOULDING	Not Necessary	128.00 FL	*- FL
9	1		*RHF DOOR OUTER HANDLE	Not Necessary	485.00 FL	*- FL
10	1		*RHF DOOR HINGE UPPER	Not Necessary	208.00 FL	*- FL
11	1		*RHF DOOR HINGE LOWER	Not Necessary	208.00 FL	*- FL
12	1		*RHF DOOR LIMITER	Not Necessary	90.00 FL	*- FL
13	1		*RHF DOOR STRIKER	Not Necessary	49.00 FL	*- FL
14	1		*RHF DOOR LATCH	Damaged	619.00 FL	*619.00 FL
15	1		*RHF DOOR INNER TRIM BOARD	Cracked	1,268.00 FL	*1,268.00 FL
16	1		*RHF DOOR INNER TRIM BOARD CLIPS	Necessary	60.00 FL	*30.00 FL
17	1		*RHF DOOR WINDOW REGULATOR WITH MOTOR	Damaged	586.00 FL	*586.00 FL
18	1		*RHF DOOR INNER WIRING HARNESS	Not Necessary	495.00 FL	*- FL
19	1		*RHR DOOR	Distorted	2,398.00 FL	*2,398.00 FL
20	1		*RHR DOOR BLACK STICKER	Necessary	92.00 FL	*92.00 FL
21	1		*RHR DOOR OUTER GLASS RUN	Not Necessary	83.00 FL	*- FL
22	1		*RHR DOOR CHROME MOULDING	Not Necessary	274.00 FL	*- FL
23	1		*RHR DOOR OUTER HANDLE	Not Necessary	485.00 FL	*- FL
24	1		*RHR DOOR HINGE UPPER	Bent	71.00 FL	*71.00 FL
25	1		*RHR DOOR HINGE LOWER	Bent	183.00 FL	*183.00 FL
26	1		*RHR DOOR LIMITER	Not Necessary	210.00 FL	*- FL
27	1		*RHR DOOR STRIKER	Not Necessary	49.00 FL	*- FL
28	1		*RHR DOOR LATCH	Damaged	255.00 FL	*255.00 FL
29	1		*RHR DOOR INNER TRIM BOARD	Cracked	1,268.00 FL	*1,268.00 FL
30	1		*RHR DOOR INNER TRIM BOARD CLIPS	Necessary	60.00 FL	*30.00 FL
31	1		*RHR DOOR WINDOW REGULATOR WITH MOTOR	Damaged	680.00 FL	*680.00 FL
32	1		*RHR DOOR INNER WIRING HARNESS	Not Necessary	286.00 FL	*- FL
33	1		*RHR FENDER	Repair	2,133.00 FL	*- FL
34	1		*RHR FENDER CHROME GARNISH	Not Necessary	535.00 FL	*- FL
35	1		*RHR QUARTER GLASS WITH MOULDING	Not Necessary	186.00 FL	*- FL
36	1		*RHR FENDER LINER	Not Necessary	137.00 FL	*- FL
37	6		*RHR FENDER LINER CLIPS	Not Necessary	36.00 FL	*- FL
38	1		*REAR BUMPER	Torn	1,417.00 FL	*1,417.00 FL
39	1		*RHR BUMPER BRACKET	Not Necessary	90.00 FL	*- FL
40	1		*RHR ABSORBER	Not Necessary	182.00 FL	*- FL
41	1		*RHR WHEEL HUB AND BEARING	Not Necessary	827.00 FL	*- FL
42	1		*RHR TYRE	Not Necessary	280.00 FS	*- FS
43	1		*RHF DOOR OUTER HANDLE BASE	Cracked	210.00 FL	*210.00 FL
44	1		*RHR DOOR OUTER HANDLE BASE	Cracked	91.00 FL	*91.00 FL
45	1		*RHR DOOR GLASS RAIL	Cracked	50.00 FL	*50.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,939.00	11,375.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,965.90	1,137.50
Total Parts (\$)	17,973.10	10,237.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,950.00	650.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	1,650.00	1,100.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	195.00	30.00
4	S.R.S RESET OF SYSTEM	New	300.00	250.00
5	TO CONDUCT TRANSFER FRONT DOOR MECHANISM TO NEW DOOR PANEL	New	195.00	150.00
6	TO APPLY DOOR SEALANT TO DOOR	New	195.00	60.00
7	TO REMOVE AND REFIT AUDIO SPEAKER	New	195.00	0.00
8	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	3,900.00	1,300.00
9	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	2,750.00	2,200.00
10	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	195.00	30.00
11	REMOVE AND REFIX SEAT CUSHION /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	325.00	120.00
12	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	195.00	60.00
13	TRANSFER OF INTERNAL MECHANISM FROM OLD DOOR PANEL TO NEW DOOR PANEL	New	195.00	150.00
14	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	195.00	0.00
15	TO APPLY DOOR SEALANT TO DOOR	New	130.00	60.00
16	REMOVE AND REPLACE RHR UNDER CARRIAGE PARTS	New	325.00	0.00
17	TO CONDUCT 4 WHEEL ALIGNMENT	New	120.00	0.00
18	TO REMOVE AND REFIT FUEL TANK TO FACILITATE ACCIDENT REPAIR	New	195.00	0.00
19	TO REMOVE AND REIFT REAR WINDSCREEN DUE TO REPLACEMENT OF REAR FENDER	New	120.00	0.00
20	TO REMOVE AND REFIX REAR QUARTER GLASS	New	130.00	0.00
Gross Labour Cost (\$\$)			13,455.00	6,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >