

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7237M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CUT	459.40	459.40
2	REAR BUMPER SIDE BRACKET LH/RH @\$55.80	NECESSARY	111.60	111.60
1	REAR BUMPER REINFORCEMENT	BENT	394.80	394.80
2	REAR BUMPER REINFORCEMENT STAY LH/RH @\$138.10	SERVICEABLE	276.20	-
1	REAR BUMPER CENTRE MOULDING	SCRATCHED	451.25	451.25
1	REAR BUMPER TOW COVER	SERVICEABLE	94.60	-
1	REAR BUMPER FOG LAMP	SERVICEABLE	201.50	-
2	REAR NUMBER PLATE LAMP @\$85.30	SERVICEABLE	170.60	-
2	REAR BUMPER REFLECTOR LH/RH @\$41.45	O/S CRACKED / N/S SERVICEABLE	82.90	41.45
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-452.97	-296.10
			1,811.88	1,184.40
	NETT ITEMS			
1	REAR REVERSE SENSOR (N)	сит	180.00	180.00
1	REAR BUMPER NUMBER PLATE W/HOLDER (N)	NECESSARY	55.00	55.00
	LESS 10% DISCOUNT		-23.50	-23.50
			211.50	211.50
	<u>LABOUR</u>			
	PANEL BEATING.		500.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK LIGHTING AND WIRING.		60.00	20.00
	TUFF KOTE.		60.00	20.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	20.00
			980.00	660.00
	GRAND TOTAL		3,003.38	2,055.90





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,650.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22001561/Vqy3n2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser