

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7314M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	DENTED	553.00	553.00
2	REAR BUMPER BRACKET SIDE LH/RH @\$35.60	NECESSARY	71.20	71.20
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
2	REAR BUDMPER REFLECTOR LH/RH @\$32.00	DISTORTED	64.00	64.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	428.40	-
1	REAR BUMPER UNDER COVER	DISTORTED	228.00	228.00
1	REAR END PANEL	SERVICEABLE	495.50	-
1	END PANEL GARNISH	SERVICEABLE	57.70	-
1	BOOTLID	DENTED	2,609.80	2,609.80
1	BOOTLID LOWER GARNISH	SERVICEABLE	227.90	-
2	BOOTLID HINGES LH/RH @\$142.30	SERVICEABLE	284.60	-
1	BOOTLID MOULDING	NECESSARY	85.00	85.00
1	BOOTLID CDRI	NECESSARY	52.40	52.40
1	BOOTLID EMBLEM 140	NECESSARY	67.90	67.90
	LESS 20% DISCOUNT		-1,049.48	-750.66
			4,197.92	3,002.64
	SPECIAL NETT ITEMS			
1	BOOTLID CITYCAB & TEL NO STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	REVERSE SENSOR (SN)	CUT	135.70	135.70
			245.70	245.70
	<u>LABOUR</u>			
	PANEL BEATING.		750.00	560.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	20.00
	CHECK LIGHTING.		60.00	20.00



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.		90.00	30.00
			1,560.00	1,130.00
	GRAND TOTAL		6,003.62	4,378.34

RECOMMENDED COST OF LUMP SUM REPAIRS		3,500.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22001563/Vty3n2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser