


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD/TP/WS/TPRES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No _____
 Claims No. **MT/1160527-002**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs. 2 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Veh No: SHC2104k Yr Regn: 25/1/17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / (Tax) / Prime Mover /
 Truck / Trailer or
 Make: Hyundai 140 c.c. 1685
 Colour: blue AC: Insured / Std / NI / NA
 Sp. Reading: 733060 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHCBULUMHU098562
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: Nil / (SRM) / STD A/Rlm or
 Tyre Size: F: 206/60R16
 R: 206/60R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlanc
 Front: _____ Rear: _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 4/2/22 D.O.I. 4/2/22 1630
 Survey held at CDGE
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>No GSA given</u>
	LUMP SUM \$1100,2DAYS
	RED:1054.81:48%

Date/Time File Pass to? ☐ : Prell. Report
 1) ☐ : Final Report
 Date/Time File Return to? _____

Days Of Repair: 2
 Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : VV&E (\$ _____)

Survey Fee: _____
 Transportation: _____
 \$ + RS. \$ _____
 Final: _____
 Other: _____
 Total: _____

Request Form: _____
 Date: _____

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
 205, Orchard Road, Singapore 238591
 Maresham Road, Singapore 650280
 Workshops
 205, Orchard Road, Singapore 238591
 50, Loo Lay Road, Singapore 500049
 103, Sunning Road, Singapore 117517

Date/Time: 04.02.2022 12:56

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4170279

JC NO 305503593

CUSTOMER

MR/MS COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO 7010045

ADDRESS 383 SIN MING DRIVE
 Singapore SINGAPORE 575717

TEL (R) 65508755 (O)
 (P)

DISCOUNT CARD NO


REGN NO: SHC2104K	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....
MODEL: I-40	DATE/TIME IN 04.02.2022 09:55
YR OF MANUF. 25.01.2017	TARGET DATE
CHASSIS CODE KMHLEB41UMHU098562	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 04.02.2022
 NATURE: 3P 04.02.2022

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

ame:

No.:

Vehicle No.: SHC2104K

CHIANG

Name of Service Advisor

Signature/Date

Exit Pass

Vehicle No.:

SHC2104K

Name of Service Advisor

Date

to be returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO. ~~SHA6916T~~ *SHC 210416*

04/02/22

MAKE/REG 25.01.2017

MODEL HYU- I40

CHIANG/ NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$553.00
1	REAR BUMPER LOWER COVER			\$228.00
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER REFLECTOR RH			\$32.00
2	REAR BUMPER BRACKET SIDE /RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
				\$1,334.60
				\$266.92
				\$1,067.68
1	REAR BUMPER MAT			\$50.00
1	REVERSE SENSOR			\$135.70
		10.00%		\$167.13
	Labour Charge			
	Panel Beating /REAR			\$500.00
	Spray Painting Charge /REAR			\$300.00
	Remove/refix reverse sensor			\$60.00
	Tuff Kote			\$60.00
				\$920.00
	ESTIMATE TOTAL			\$2,154.81
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Theran
82238769
4/2/22 1630
48 after repair photo
2clays wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: