

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001568/VVY3Q2**Date:** 18/08/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00049562100

Claimant Vehicle No : SMU5929Z**Insured Vehicle No :** YQ594S

Date of Loss: 03/02/2022

Nature of Claim: TP

Claim No: SNM22D201200/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMU5929Z**

Make & Model: MERCEDES-BENZ C200, 2.0 (A)

Engine No: 27492030176835

Reg. Date: 24/07/2014 (Man. Year: 2014)

Chassis No: WDD2050422F021949

Colour: Grey

Odometer: 0 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,575.00	10,096.60	7,478.40	42.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	1,010.00	2,820.00	73.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,405.00	11,106.60	10,298.40	48.11
Approved Total (Overridden) (S\$)		8,900.00		
Nett Amount (S\$)	21,405.00	8,900.00	12,505.00	58.42

INSPECTION

Date of Assignment: 17/08/2022

Date Inspected: 18/02/2022 Inspected At:

JEW Motors (HQ)
60 Jalan Lam Huat Carros Centre #03-72
Singapore 737869

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Aug 2022)
Parts:	143	MERCEDES-BENZ C200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU5929Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	2,114.00 FL	*- FL
2	1		*BONNET EMBLEM	Necessary	108.00 FL	*108.00 FL
3	1		*BONNET RH HINGE	Repair	266.00 FL	*- FL
4	1		*BONNET LH HINGE	Repair	266.00 FL	*- FL
5	1		*BONNET INNER INULATOR	Serviceable	239.00 FL	*- FL
6	1		*SET BONNET INNER INULATOR CLIPS	Necessary	70.00 FL	*70.00 FL
7	1		*BONNET RH LOCK	Jammed	78.00 FL	*78.00 FL
8	1		*BONNET RH LOCK CATCH	Bent	68.00 FL	*68.00 FL
9	1		*BONNET LH LOCK	Jammed	78.00 FL	*78.00 FL
10	1		*BONNET LH LOCK CATCH	Bent	68.00 FL	*68.00 FL
11	1		*BONNET LOCK BRACKET	Bent	89.00 FL	*89.00 FL
12	1		*FRONT BUMPER (AMG)	Cut	1,580.00 FL	*1,580.00 FL
13	1		*FRONT BUMPER TOWING COVER	Repair	78.00 FL	*- FL
14	1		*FRONT BUMPER NUMBER PLATE HOLDER	Cut	145.00 FL	*145.00 FL
15	1		*FRONT BUMPER TOP RUBBER	Serviceable	168.00 FL	*- FL
16	1		*FRONT BUMPER TOP BEAM	Serviceable	224.00 FL	*- FL
17	1		*FRONT BUMPER REINFORCEMENT	Dented	782.00 FL	*782.00 FL
18	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	101.00 FL	*101.00 FL
19	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	101.00 FL	*101.00 FL
20	1		*FRONT BUMPER LOWER GRILLE	Cut	232.00 FL	*232.00 FL
21	1		*FRONT BUMPER RH SENSOR	Cut	239.00 FL	*239.00 FL
22	1		*FRONT BUMPER LH SENSOR	Cut	239.00 FL	*239.00 FL
23	1		*RH HEADLAMP ASSY	Cracked	3,231.00 FL	*3,231.00 FL
24	1		*LH HEADLAMP ASSY	Cracked	3,231.00 FL	*3,231.00 FL
25	1		*FRONT GRILLE EMBLEM BASE	Cut	438.00 FL	*438.00 FL
26	1		*FRONT GRILLE EMBLEM CHROME	Scratched	145.00 FL	*145.00 FL
27	1		*FRONT GRILLE BASE	Cut	151.00 FL	*151.00 FL
28	1		*FRONT RADAR SENSOR	Serviceable	1,177.00 FL	*- FL
29	1		*FRONT RADAR SENSOR COVER	Serviceable	32.00 FL	*- FL
30	1		*FRONT SUPPORT PANEL	Repair	745.00 FL	*- FL
31	1		*FRONT SUPPORT PANEL COVER	Serviceable	46.00 FL	*- FL
32	1		*AIRCON CONDENSER	Serviceable	1,550.00 FL	*- FL
33	1		*RADIATOR	Serviceable	1,271.00 FL	*- FL
34	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
35	1		*FRONT NUMBER PLATE	Cracked	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,510.00	11,214.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,935.00	1,117.40
Total Parts (\$)	17,575.00	10,096.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REPLACE PARTS AND ALL AFFECTED AREAS	New	1,200.00	400.00
2	SPRAY PAINTING ON ALL AFFECTED PARTS AND AREAS	New	1,000.00	400.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	120.00	30.00
4	APPLY RUST COATING ON AFFECTED AREAS	New	100.00	30.00
5	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES	New	280.00	0.00
6	REMOVE AND REPLACE RADIATOR AND HOSES	New	280.00	0.00
7	REFOCUS AND ADJUST HEADLAMPS ASSY	New	120.00	50.00
8	RESET AND PROGRAMMING CONTROL UNIT	New	550.00	60.00
9	REMOVE AND REPLACE FRONT BUMPER SENSORS	New	180.00	40.00
Gross Labour Cost (\$)			3,830.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >