

ComfortDelGro Engineering

### 205 Braddell Road S(579701)

	ACCIDENT R	EPAIR ESTIMATES				
Our Ref:						
Type of Claim :TF	<b>.</b>	Vehicle No.	PC8289B			
		Make & Model Year of Manufacture Chassis No.	TOYOTA HIACE  JTFGT22P100039550			
Ins Company : NTUC VS CHI Excess :  Date of Accident : 2/14/2		Engine No. Policy No. Time of Accident	1750			
Suggested Days of Repair		In-house Vehicle Asse	essor			
Repair Estimates   Repair Estimates   \$ 4,372.60     Parts (a) Cost / List Price Items   \$ 4,372.60     Plus/Less   25%   \$ 1,093.15     Total of Cost / List   \$ 3,279.45     (b) Nett Price Items   \$ -		Case Owner :  Signature :  Contact No Frt Counter Operation  Brenda Tel: 63837730 email: brendang@sparkcarcare.com Rohani tel: 63837890 email: rohanim@sparkcarcare.com  Back-end Operation Ngo Toh Wee Tel: 63837656 email: ngotw@sparkcarcare.com Patrick Tel: 63837466 email: patricktia@sparkcarcare.com				
The above total will be subjected to 79  Name of Surveyor  Company	% G.S.1.					

## **Spark Car Care**

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

#### **Spare Parts**

Vehicle No	:	PC8289B	Case Owner	•	0
Make & Model	:	TOYOTA HIACE	Year Manufacture	:	0
Chassis No	:	JTFGT22P100039550	Engine No	7.50.5	0
Sales Order	ŝ		Supplier		
Order By			Type of Claim	:	TP

S/Nc	Part Description	QTY	Cost		List	Nett	T		Disposition By
	2000/ipaon		Price		Price	Price	S/N		Surveyor
1	TAILGATE	1		\$	2,375.30				
2	TAILGATE GLASS MOULING	1			NA				
3	TAILGATE LOCK	1		\$	279.50				
4	TAILGATE WEATER STRIP	1		\$	474.90				
5	TAILGATE STICKER' TOYOTA'	1		\$	72.10				
6	TAILGATE STICKER 'HIACE'	1			W05				
7	STICKER 60KM/H	1					\$	15.00	
8	STICKER 'WWW.MINGCHUANSG.COM'	1					\$	250.00	
9	STICKER REFLECTOR	1					\$	50.00	
10	SEALANT	1					\$	40.00	
11	INNER SEAL	1					\$	30.00	
12	TAILLAMP LH	1		\$	367.60				
13	TAILLAMP RH	1		\$	367.60				
14	REAR BUMPER	0		\$	435.60				
15	REAR BUMPER SENSOR	0					\$	280.00	
16	0	0					<u> </u>	200.00	
17	0	0							
18	0	0							
19	0	0							
20	0	0							
21	0	0					1		
22	0	0							
23	0	0							
24	0	0					-		
25	0	0		1 -			<b>†</b>		
26	0	0					-		
27	0	0						-	
28		0							
29		0					1		
30		0					-		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# **Spark Car Care**

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

### <u>Labour</u>

Vehicle No.	PC8289B	Case Owner	: 0	
Make & Model :	TOYOTA HIACE	Year of Manufacture	: 0	

S/No	Labour Description	Esimated	Adjusted	
		Price	Price	
	TO REMOVE AND INSTALL TAILGATE GLASS	\$120.00		
	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUSH AS			
	TAILGATE, REAR BUMPER, REAR END PANEL AND ETC	\$960.00		
	TO PUTTY AND RESRPAY ACCIDENT AREA SUCH AS TAILGATE,			
	REAR BUMPER, REAR END PANEL AND ETC	\$800.00		
	TO TRANSFER TAILGATE INNER PARTS FROM DAMAGE TO NEW	\$150.00		
	TO CHEC WIRING AND LIGHTING	\$50.00		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.