

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001569/KVY3N2**Date:** 08/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00077972100

Claimant Vehicle No : PC8289B **Insured Vehicle No :** GBL2171P

Date of Loss: 14/02/2022 Nature of Claim: TP Claim No: SNM22D201203/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC8289B**

Make & Model: TOYOTA HIACE, 3.0 D HIGH ROOF COMMUTER TURBO (A) Engine No: 1KD2850861

Reg. Date: 24/06/2019 (Man. Year: 2019) Chassis No: JTFST22P100039550

Colour: Metallic Silver Odometer: 64699 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15X8 Rear Tyre Size: 195R15X8

Front Left Side: Michelin 3 mm Rear Left Side: Austone 9 mm

Front Right Side: Michelin 3 mm Rear Right Side: Austone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,944.45	3,330.85	613.60	15.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,470.00	610.00	29.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,024.45	4,800.85	1,223.60	20.31
+ GST 7.00/7.00% (S\$)	421.71	336.06	85.65	20.31
Nett Amount (S\$)	6,446.16	5,136.91	1,309.25	20.31

INSPECTION

Date of Assignment: 21/02/2022

Date Inspected: 18/02/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
205 Braddell Road
Singapore 579701

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Mar 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D HIGH ROOF COMMUTER TURBO (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC8289B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,375.30 FL	*2,151.10 FL
2	1		*TAILGATE LOCK	Jammed	279.50 FL	*279.50 FL
3	1		*TAILGATE WEATHER STRIP	Cut	474.90 FL	*381.90 FL
4	1		*TAILGATE STICKER TOYOTA }	Necessary	72.10 FL	*72.10 FL
5	1		*TAILGATE STICKER HIACE }		0.00 FL	*- FL
6	1		*TAILLAMP LH	Serviceable	367.60 FL	*- FL
7	1		*TAILLAMP RH	Damaged	367.60 FL	*367.60 FL
8	1		*REAR BUMPER	Buckled	435.60 FL	*435.60 FL
9	1		*STICKER 60KM/H	Necessary	15.00 FS	*15.00 FS
10	1		*STICKER WWW.MINGCHUANSG.COM.	Necessary	250.00 FS	*150.00 FS
11	1		*STICKER REFLECTOR	Necessary	50.00 FS	*50.00 FS
12	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
13	1		*INNER SEAL	Necessary	30.00 FS	*30.00 FS
14	1		*REAR BUMPER SENSOR	Dented	280.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,037.60	4,252.80
- List Item Discount on L Items 25.00/25.00% (\$)	1,093.15	921.95
Total Parts (\$)	3,944.45	3,330.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL TAILGATE GLASS	New	120.00	120.00
2	TO KNOCK,STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS TAILGATE,REAR BUMPER,REAR END PANEL AND ETC	New	960.00	600.00
3	TO PUTTY AND RESPRAY ACCIDENT AREA SUCH AS TAILGATE,REAR BUMPER,REAR END PANEL AND ETC	New	800.00	650.00
4	TO TRANSFER TAILGATE INNER PARTS FROM DAMAGE TO NEW	New	150.00	80.00
5	TO CHECK WIRING AND LIGHTING	New	50.00	20.00
Gross Labour Cost (\$)			2,080.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >