



ComfortDelGro Engineering

205 Braddell Road S(579701)

Our Ref:

ACCIDENT REPAIR ESTIMATES

Type of Claim :

TP

Vehicle No.

PC8289B

Make & Model

TOYOTA HIACE

Year of Manufacture

Chassis No.

JTFTGT22P100039550

Engine No.

Policy No.

Time of Accident

1750

In-house Vehicle Assessor

Case Owner

Signature

Contact No

Frt Counter Operation

Brenda Tel: 63837730 email: brendang@sparkcarcare.com

Rohani Tel: 63837890 email: rohanim@sparkcarcare.com

Back-end Operation

Ngo Toh Wee Tel: 63837656 email: ngotw@sparkcarcare.com

Patrick Tel: 63837466 email: patricktia@sparkcarcare.com

Repair Estimates

Parts (a) Cost / List Price Items \$ 4,372.60

Plus/Less 25% \$ 1,093.15

Total of Cost / List \$ 3,279.45

(b) Nett Price Items \$ -

Less

Total of Nett Item

(c) Special Nett Items \$ 665.00

Total Parts Cost (Appendix A) \$ 3,944.45

Labour (Appendix B) \$ 2,080.00

Total Repair Cost \$ 6,024.45

The above total will be subjected to 7% G.S.T.

Not Authorized
Preliminary Repair

5 days

84800.85

Name of Surveyor

Company

Survey conducted on

Kenneth

CIC

18/2/22

at

Remarks By Surveyor(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor

Date:

18/2/22

ACCIDENT REPAIR ESTIMATES/F3

COMPLETE VMS PTE LTD

is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which
may be require after the work has begin

• Supplementary item(s) must be approved by
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Spare Parts

Vehicle No : PC8289B Case Owner : 0
 Make & Model : TOYOTA HIACE Year Manufacture : 0
 Chassis No : JTFGT22P100039550 Engine No : 0
 Sales Order : _____ Supplier : _____
 Order By : _____ Type of Claim : TP

Spark Car Care
 ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62815767

Page 1

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	TAILGATE <i>2151.10</i>	1	<i>Pa</i>	\$ 2,375.30			✓
2	TAILGATE GLASS MOULING	1		NA			
3	TAILGATE LOCK	1	<i>Ja</i>	\$ 279.50			✓
4	TAILGATE WEATER STRIP <i>381.90</i>	1	<i>Ja</i>	\$ 474.90			✓
5	TAILGATE STICKER 'TOYOTA'	1	<i>Ja</i>	\$ 72.10			✓
6	TAILGATE STICKER 'HIACE'	1		W05			
7	STICKER 60KM/H	1			<i>Ja</i>	\$ 15.00	✓
8	STICKER 'WWW.MINGCHUANGS.COM'	1			<i>Ja</i>	\$ 250.00	<i>1501a</i>
9	STICKER REFLECTOR	1			<i>Ja</i>	\$ 50.00	✓
10	SEALANT	1			<i>Ja</i>	\$ 40.00	✓
11	INNER SEAL	1			<i>Ja</i>	\$ 30.00	✓
12	TAILLAMP LH	1	<i>Ja</i>	\$ 367.60			X
13	TAILLAMP RH	1	<i>Ja</i>	\$ 367.60			X
14	REAR BUMPER	0	<i>Bu</i>	\$ 435.60			✓
15	REAR BUMPER SENSOR	0			<i>Ja</i>	\$ 280.00	✓
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

17/02/2022

9:04 AM

for the work has been
 Preliminary inspection and does not cover additional parts and labour time which
 Signature: _____
 Date: _____

Spark Car Care
ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No. _____

Make & Model :

PC8289B

TOYOTA HIACE

Case Owner

Year of Manufacture

0

0

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Acknowledged by Repairer

Signature: _____

Date: _____