

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/MSG22001570/UVF3N2**Date:** 03/03/2022**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001618367
Claimant Vehicle No :	SMY6460E	Insured Vehicle No :	SMD479C
Date of Loss:	16/02/2022	Nature of Claim:	TP
		Claim No:	269970

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY6460E	Engine No:	L13B3941467
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Chassis No:	GK33426977
Reg. Date:	18/03/2021 (Man. Year: 2019)	Odometer:	10350 km
Colour:	Blue		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,874.70	3,962.60	12,912.10	76.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,610.00	2,350.00	3,260.00	58.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,484.70	6,312.60	16,172.10	71.92
+ GST 7.00/7.00% (S\$)	1,573.93	441.88	1,132.05	71.93
Nett Amount (S\$)	24,058.63	6,754.48	17,304.15	71.92

INSPECTION

Date of Assignment:	28/02/2022		Fastech Auto Pte Ltd (HQ)
Date Inspected:	17/02/2022	Inspected At:	1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Estimated Period of Repair:	5.0 days		Singapore 417883

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2022)
Parts: 143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMY6460E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,430.00 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	106.00 F	*86.20 FL
3	1		*TAILGATE	Badly Dented	945.20 F	*779.20 FL
4	1		*TAILGATE FIT EMBLEM	Necessary	68.50 F	*55.00 FL
5	1		*TAILGATE OUTER HANDLE GARNISH	Warped/Cracked	245.60 F	*244.30 FL
6	2		*TAILGATE REFLECTORS	Serviceable	410.00 F	*- FL
7	1		*TAILGATE INNER LOCK	Bent	185.20 F	*185.20 FL
8	1		*TAILGATE INNER TRIM BOARD	Deformed/Cracked	366.20 F	*341.20 FL
9	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 F	*30.00 FL
10	1		*TAILGATE WEATHERSTRIP	Twisted	165.00 F	*148.50 FL
11	2		*TAILGATE STOPPERS	Not Necessary	30.00 F	*- FL
12	1		*TAILGATE H LOGO	Necessary	28.00 F	*28.00 FL
13	2		*TAILGATE DAMPERS	Not Necessary	360.00 F	*- FL
14	1		*TAILGATE REAR WIPER MOTOR	Not Necessary	450.00 F	*- FL
15	1		*TAILGATE REAR WIPER ARM	Not Necessary	162.00 F	*- FL
16	1		*TAILGATE LICENCE PLATE LAMP	Not Necessary	60.00 F	*- FL
17	1		*REAR BUMPER	Distorted	827.00 F	*492.70 FL
18	2		*REAR BUMPER SIDE RETAINERS	Bent	56.00 F	*56.00 FL
19	1		*REAR BUMPER LOWER CENTRE MOULDING	Cut	108.00 F	*108.00 FL
20	2		*REAR BUMPER LOWER SIDE MOULDINGS	Cut	170.00 F	*170.00 FL
21	2		*REAR BUMPER SPLASH SHIELDS	Not Necessary	176.00 F	*- FL
22	1		*REAR BUMPER LOWER	No such part	250.00 F	*- FL
23	1		*REAR END PANEL	Badly Dented	465.00 F	*345.20 FL
24	1		*REAR END PANEL TOP GARNISH	Twisted	182.00 F	*145.80 FL
25	2		*TAILLAMPS	Cracked	1,180.00 F	*690.00 FL
26	2		*TAILLAMP HOUSING PANELS	Repair	580.00 F	*- FL
27	1		*REAR FLOOR PANEL	Repair	1,280.00 F	*- FL
28	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	435.00 F	*- FL
29	1		*REAR FLOOR PANEL TOOLS SPONGE	Not Necessary	608.00 F	*- FL
30	1		*REAR FLOOR PANEL SPARE TYRE LOCK BOLT	Not Necessary	50.00 F	*- FL
31	1		*REAR COMPARTMENT BLIND TOP COVER	Not Necessary	650.00 F	*- FL
32	1		*REAR FENDER INNER TRIM BOARDS	N/s Deformed	700.00 F	*315.20 FL
33	2		*REAR FENDERS	Repair	1,920.00 F	*- FL
34	1		*REAR EXHAUST	Not Necessary	545.00 F	*- FL
35	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	108.00 F	*- FL
36	1		*REAR EXHAUST MOUNTING	Not Necessary	50.00 F	*- FL
37	1		*REAR BUZZLE SENSOR	Cracked	98.00 F	*98.00 FL
38	1		*REAR ANTENNA SENSOR	Shorted	155.00 F	*128.50 FL
39	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
40	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
41	1		*REAR LICENCE PLATE	Scratched	50.00 FS	*40.00 FS
42	1		*SET REAR REVERSE CAMERA	Serviceable	450.00 FS	*- FS
43	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
44	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
45	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
46	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
47	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	35.00 FS	*- FS	
48	1		*REAR EDITIONSTICKER	Not Necessary	60.00 FS	*- FS	
					Sub Total (\$\$)	16,874.70	4,852.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	889.40
					Total Parts (\$\$)	16,874.70	3,962.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
8	TO DISMANTLE & REFIX ROOF LINING FOR FACILITATE REPAIR ROOF PANEL	New	180.00	0.00
9	TO RESET & REPROGRAMME,DIAGNOSIS SYSTEM	New	200.00	60.00
10	TO SPRAY RUST PROOFING	New	200.00	60.00
11	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,500.00	800.00
12	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,100.00
			Gross Labour Cost (\$\$)	5,610.00
				2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >