

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 3732P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE (WCP)	TO REPAIR SEE LABOUR	950.00	-
1	TAILGATE MIRROR BRACKET (WCP)	BENT	170.00	170.00
1	TAILGATE GLASS (WCP)	BROKEN	600.00	600.00
1	TAILGATE "NV200" EMBLEM (WCP)	NECESSARY	42.00	42.00
1	REAR FENDER RH (WCP)	TO REPAIR SEE LABOUR	1,350.00	-
	COST PLUS 10%		311.20	81.20
			3,423.20	893.20
	SPECIAL NETT ITEMS			
1	SET TAILGATE GLASS INNER SEAL (SN)	NECESSARY	20.00	20.00
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	TAILGATE "70KM/H" STICKER (SN)	NECESSARY	20.00	10.00
1	TAILGATE "6PAX" STICKER (SN)	NECESSARY	20.00	10.00
			100.00	80.00
	<u>LABOUR</u>			
	TO TRANSFER TAILGATE FITTING.		120.00	40.00
	TO REMOVE AND REFIX TAILGATE GLASS.		120.00	120.00
	TO CLEAN AND VACUUM.	NOT NECESSARY	50.00	-
	TO CHECK WIRING FUNCTION.	NOT NECESSARY	30.00	-
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR FENDER RH.		450.00	400.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		550.00	400.00
			1,320.00	960.00
	GRAND TOTAL		4,843.20	1,933.20



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		1,933.20
LESS EXCESS		-500.00
NETT LIABILITY		1,433.20

Report Ref No. CS/UOI22001579/Rtf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X.2.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser