



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22001581/Evy3m4 Date: 25/01/2023 Code: FCI2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	FBK 6180S
Policy No.	D-21097290MFCE/111	Coverage (\$)	0.00
Claim No.	D21001682MFCE	Excess (\$)	1,500.00
Assign From	AINI BINTE	Assign Date	18/02/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA CB400X	c.c	399
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JH2NC4795EK000328	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/55 R17	BRIDGESTONE	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/55 R17	BRIDGESTONE	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/05/2021	Inspection Date	18/02/2022
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD NO : 320 UBI ROAD 3 SINGAPORE 408649		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE MARKET VALUE IS S\$8,000.00(EST. AVERAGE) C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	