

**ComfortDelGro Engineering Pte Ltd**  
59 Loyang Drive Singapore 508969

Our Ref : 305490842 Via Fax : Email  
Date : 18 02 22 Your Insured : SDU 54L  
Time of Fax : \_\_\_\_\_ Date of Acc : 24 09 2021  
Attn: Motor Claims Department MSIG

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH**

A9377D

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811	} <b>limts@cde.com.sg</b> <b>Fax no. 6546 8156</b>
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	
◆ <u>Lim Tien Siong</u>	<b>Tel: 6214 8398 or HP: 9635 8546</b>	
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

For Vice President  
Taxi Accident Repair


## JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

### Job Requisition

1. Date: <u>17/05/22</u> Time Received: <u>09:55hrs</u>		3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)	4. Type of Towing: <input type="checkbox"/> Normal Tow <input checked="" type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : <u>Ms Catherine</u> Contact No. : <u>6244 8313</u> Vehicle No. : <u>SHA 9377D</u> Make / Model / Colour : <u>140</u> Email : <u>140</u>		5. Nature of Service: <input type="checkbox"/> Jumpstart <input checked="" type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery	6. Parts Replaced/Remarks:
7. Location: <u>S17 Airport Road (Traffic Pound)</u>		8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi	
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others: _____			

10. Odometer Reading : \_\_\_\_\_  
Fuel Level : ☐ F ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ E

11. Radio / CD Player  
☐ OK  
☐ Faulty  
☐ Not tested



# : Cracked X : Dented  
/ : Scratched O : Missing

Signature of Customer

### Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☒ GAO ☐ OTHERS  
Name of Driver : Neer An  
Vehicle No. : YK 3697R  
Time Dispatch : 09:55hrs  
Time of Arrival : 10:15hrs  
Time Completed : \_\_\_\_\_

### Cash Invoice Details (if applicable)

13. Cash Invoice No. : \_\_\_\_\_

### Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.  
b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.  
c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

Date

Time

Signature of Customer

### 14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

**CUSTOMER'S COPY**

# COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

## REPAIR ESTIMATE

PAGE 1 of 3

DATE: **18-Feb-22**

INSURANCE: **MSIG**

MODEL: **Hyundai i40 (FRONT)**

MVA: **LIM T S**

VEHICLE NO.: **SHA9377D**

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Bonnet	1		\$2,265.90
	Bonnet Rubber (LH)	1		\$35.70
	Bonnet Rubber (RH)	1		\$35.70
	Bonnet Hinge (LH/RH)	2	\$126.70	\$253.40
	Bonnet Moulding	1		\$105.20
	Bonnet Lock	1		\$142.20
	Bonnet Absorber (LH/RH)	2	\$61.60	\$123.20
	Bonnet Insulator	1		\$202.50
	Bonnet Seal	1		\$31.90
	Bonnet Insulator Clips	10	\$2.20	\$22.00
	Bonnet Cable	1		\$69.60
	Radiator Grille H Emblem	1		\$129.50
	Radiator Grille	1		\$1,480.00
	Front Bumper Cover	1		\$1,052.20
	Front Bumper Sponge	1		\$379.20
	Front Bumper Reinforcement	1		\$588.40
	Front Bumper Grille (LH/RH)	2	\$187.20	\$374.40
	Front Number Plate	1		\$35.00
	Front No. Plate Trim Cover	1		\$20.00
	Front Bumper Centre Grille	1		\$114.00
	Front Bumper Lip	1		\$152.00
	Front Bumper Bracket Top (LH/RH)	2	\$44.80	\$89.60
	Front Bumper Bracket (LH/RH)	2	\$49.20	\$98.40
	Front Bumper Side Bracket	2	\$14.30	\$28.60
	Front Bumper Grille Air Duct (LH/RH)	2	\$126.20	\$252.40
	Headlamp Support Panel Assy	1		\$907.40
	Headlamp (LH/RH)	2	\$1,388.00	\$2,776.00
	Headlamp Support Top Cover	1		\$222.60
	Radiator	1		\$1,637.20
	Radiator Fan Blade, Cowling, Motor Assy	1		\$1,194.20
	Radiator Bracket (LH/RH)	2	\$13.00	\$26.00
	Radiator Hose Upper	1		\$229.50
	Radiator Hose Lower	1		\$135.60
	Radiator Guard (LH/RH)	2	\$76.50	\$153.00
	Horn Unit (LH/RH)	2	\$73.80	\$147.60
	Horn Wire	1		\$156.60
	Air Cleaner Assy	1		\$118.60
	Air Filter	1		\$63.70
	Air Cleaner Cover	1		\$47.80
	Air Duct	1		\$171.70
	Air Flow Sensor	1		\$527.80
	Resonator Tank Hose	1		\$218.30

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FRONT PORTION			SHA9377D	PAGE 2 of 3
	Frt Fender RH/LH	2	\$663.00	\$1,326.00
	Frt Fender Shield RH/LH	2	\$174.90	\$349.80
	Wiper Container	1		\$61.90
	Wiper Container Motor	1		\$75.00
	Front Tyre RH	1		\$216.00
	Front Wheel Rim RH	1		\$650.60
	Front Wheel Cap RH	1		\$217.20
	Front Wheel Hub RH	1		\$153.60
	Front Shock Absorber Assy RH	1		\$684.40
	Front Shock Absorber Mounting RH	1		\$217.60
	Front Shock Absorber Fork RH	1		\$212.15
	Front Suspension Upper Arm RH	1		\$250.40
	Front Drive Shaft RH	1		\$2,061.60
	Rack & Pinion Assy	1		\$1,820.00
	STG Tid End RH	1		\$125.20
	STG Ball Joint RH	1		\$73.10
	Stabilizer Bar	1		\$463.70
	Stabilizer Bar Link RH	1		\$85.90
	Stabilizer Bracket RH	1		\$24.00
	Front Suspension Lower Arm RH	1		\$595.90
	Knuckle Arm RH	1		\$552.00
	Knuckle Arm Bearing RH	1		\$673.20

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	<b>FRONT PORTION</b>		<b>SHA9377D</b>	<b>PAGE 3 of 3</b>
	Engine Under Cover	1		\$334.60
	Engine Cross Member	1		\$2,094.40
	Engine Lower Cover	1		\$146.90
	Oil Cooler-Assy	1		\$267.10
	Inter Cooler	1		\$1,032.50
	Inter Cooler Mounting (2 Pcs)	2	\$25.90	\$51.80
	Hose B To Inter Cooler	1		\$229.70
	Hose C To Inter Cooler Inlet	1		\$294.50
	Pipe To Inter Cooler	1		\$167.05
	Pipe To Inter Cooler Outlet	1		\$244.50
	<b>SUB TOTAL</b>			<b>\$32,566.90</b>
	<b>LESS 20%</b>			<b>\$6,513.38</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$26,053.52</b>
	<b>Labour Charge</b>			
	Panel Beating			\$3,000.00
	Spray Painting Charge			\$2,000.00
	Wiring Charge			\$100.00
	Tuff Kote			\$100.00
	Towing Charge – King Dolly			\$150.00
	Remove/Refix Cushion & Upholstery Etc			\$150.00
	Remove/Refix Undercarriage			\$400.00
	Four Wheel Alignment			\$150.00
	Remove/Refix Radiator			\$120.00
	Remove/Refix Aircon & Refill Gas			\$150.00
	Remove/Refix Engine			\$1,200.00
	Remove/Refix Steering Rack/Wheel/Dr Shaft			\$150.00
	Diagnostic & Resetting To Erase Fault Code			\$480.00
	<b>TOTAL LABOUR</b>			<b>\$8,150.00</b>
	<b>(FRONT) ESTIMATE TOTAL</b>			<b>\$34,203.52</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

## COMFORTDELGRO ENGINEERING PTE LTD

P1/2

REPAIR ESTIMATE

DATE: 18.02.2022

3P INSURANCE: MSIG

MODEL: HYUNDAI I40 (REAR)

VEH NO.: SHA9377D

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Bootlid	1		\$2,609.80
	Bootlid Hinge (LH/RH)	2	\$142.30	284.60
	Bootlid Lock Upper	1		\$114.90
	Bootlid Lock Lower	1		\$31.70
	Bootlid Hyundai Plate	1		\$21.10
	Bootlid 'H' Emblem	1		\$63.10
	Bootlid CRDI Plate	1		\$52.40
	Bootlid I40 Emblem	1		\$67.90
	Bootlid Lamp (LH/RH)	2	\$622.20	\$1,244.40
	Bootlid Moulding	1		\$85.00
	Bootlid Lower Outer Garnish	1		\$227.90
	Rear Bumper	1		\$1,106.00
	Rear Bumper Reinforcement	1		\$428.40
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00
	Rear Bumper Side Bracket RH/LH	2	\$80.30	\$160.60
	Rear Bumper Sponge	1		\$119.50
	Rear Bumper Under Cover	1		\$228.00
	Rear Bumper Reflector RH	1		\$32.00
	Tail Lamp (LH/RH)	2	\$697.80	\$1,395.60
	Tail Lamp Quarter Panel (RH/LH)	2	\$453.00	\$906.00
	Exhaust Muffler RH/LH	2	\$967.70	\$1,935.40
	Exhaust Pipe Hanger	2	\$58.55	\$117.10
	Exhaust Pipe Centre	1		\$730.10
	Rear End Panel	1		\$526.70
	Rear End Lower Panel	1		\$495.50
	Rear End Panel Garnish	1		\$57.70
	Rear Fender RH/LH	2	\$2,171.40	\$4,342.80
	Rear Windscreen Moulding	1		\$51.80
SPARE PARTS SUB TOTAL				\$17,458.00
LESS 20%				\$3,491.60
DISCOUNTED SPARE PARTS TOTAL				\$13,966.40

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	<b>REAR PORTION</b>		<b>SHA9377D</b>	<b>PAGE 2 of 2</b>
	Bootlid ComfortDelGro	1		\$30.00
	Bootlid 65521111	1		\$30.00
	Reverse Sensor	1		\$135.70
	Rear Bumper Mat	1		\$50.00
	Rear Windscreen Sealant	2	\$46.00	\$92.00
	<b>NETT TOTAL</b>			<b>\$337.70</b>
	<b>SPARE PARTS &amp; OTHERS TOTAL</b>			<b>\$14,304.10</b>
	Panel Beating			<b>\$3,000.00</b>
	Spray Painting Charge			<b>\$2,000.00</b>
	Wiring Charge			<b>\$100.00</b>
	Tuff Kote			<b>\$120.00</b>
	Remove/Refix Cushion & Upholstery Rear			<b>\$120.00</b>
	Remove/Refix Rear Windscreen			<b>\$150.00</b>
	Remove/Refix Reverse Sensor			<b>\$120.00</b>
	Remove/Refix Exhaust Pipe			<b>\$160.00</b>
	<b>LABOUR TOTAL</b>			<b>\$5,770.00</b>
	<b>(REAR) ESTIMATE TOTAL</b>			<b>\$20,074.10</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				