#### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte.

nois insurance (Singapore) Pte. Proi

Ltd. 4 Shenton Way

#21-01 SGX Centre 2

Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Douglas Ong Chu Chong Date: 25 Feb 2022

# **Preliminary Advice**

Insured: SDU54L

Vehicle No

TP Vehicle : SHA9377D Accident Date : 24/09/2021

No . 24/09/2021

Make : HYUNDAI I40 Assignment Date : 21/02/2022

Date of : 18/02/2022 Est. Duration of

Inspection : 10/02/2022 Est. Buration of : 12

Inspection At: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

59 LOYANG DRIVE SINGAPORE 508969

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 54,277.62 Revised Amount :S\$ 30,155.94 Check Items (Estimated) :S\$ 17,795.12 Total :S\$ 47,951.06

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$

| Salvage Value     | :S\$ |
|-------------------|------|
| Margin for Repair | :S\$ |

| Remarks |
|---------|
|---------|

| ( )   | The vehicle is economical for repair   |
|-------|--|
| ( X ) | The vehicle is not economical for repair   |
| ( )   | Part-by-Part repair  |
| ( )   | Lump Sum repair  |
| ( X ) | The above survey was conducted on a 'without prejudice' basis.  Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost. |