



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 2043Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	906.00	906.00
1	FRONT BUMPER CENTRE LOWER GRILLE	NOT NECESSARY	126.00	-
1	FRONT BUMPER RH FOG LAMP	NOT NECESSARY	461.00	-
1	FRONT BUMPER RH FOG LAMP COVER	MISSING	107.00	107.00
1	FRONT BUMPER RH FOG LAMP COVER TRIM	MISSING	76.00	76.00
1	FRT BUMPER LOGO	NECESSARY	96.00	96.00
1	FRONT BUMPER RH AIR DUCT	NOT NECESSARY	55.00	-
1	HEADLAMP RH	CUT	2,596.00	2,596.00
	LESS 10% DISCOUNT		-442.30	-378.10
			3,980.70	3,402.90
	<u>SPECIAL NETT ITEMS</u>			
1	BODY WRAPPING STICKER (SN)	NECESSARY	600.00	530.00
			600.00	530.00
	<u>LABOUR</u>			
	REMOVE & REFIX FRT BUMPER,GRILLE, & ATTACHMENTS,RH HEADLAMP;KNOCKING & REPAIR FRT RH FENDER & REALIGN THE SAME.		450.00	300.00
	PUTTY & RESPRAY FRT BUMPER & ALL AFFECTED AREAS.		300.00	250.00
			750.00	550.00
	GRAND TOTAL		5,330.70	4,482.90
RECOMMENDED COST OF REPAIRS				4,482.90

Report Ref No. CS/FCI22001588/Kwy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.