



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22001588/Kwy3m4 Date: 19/04/2023  Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBJ 7839A	Veh. Inspected	SMU 2043Z
Policy No.		Coverage (\$)	0.00
Claim No.	D22000474MFCV	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	18/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	BMW 218I (A)	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WBA2M120X07D62831	Colour	RED
Odometer	32196 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/35ZR19	MICHELIN	8 mm
L/H Front Tyre	235/35ZR19	MICHELIN	8 mm
R/H Rear Tyre	255/40ZR19	MICHELIN	7 mm
L/H Rear Tyre	255/40ZR19	MICHELIN	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	17/02/2022	Inspection Date	24/02/2022
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	