

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001590/BNY3M4**Date:** 15/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00002172100

Claimant Vehicle No : SGH3S **Insured Vehicle No :** SGY4961K

Date of Loss: 12/02/2022 Nature of Claim: TP Claim No: SNM22D201122/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGH3S**

Make & Model: PORSCHE MACAN, 2.0 PDK CYP E5 (A) Engine No: 041504

Reg. Date: 25/11/2016 (Man. Year: 2016) Chassis No: WP1ZZZ95ZHLB05510

Colour: White Odometer: 82997 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/45 R20 Rear Tyre Size: 295/40 R20

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	48,386.42	17,519.55	30,866.87	63.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,540.00	2,760.00	3,780.00	57.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	54,926.42	20,279.55	34,646.87	63.08
Approved Total (Overridden) (S\$)		15,000.00		
(S\$)	54,926.42	15,000.00	39,926.42	72.69
+ GST 7.00/7.00% (S\$)	3,844.85	1,050.00	2,794.85	72.69
Nett Amount (S\$)	58,771.27	16,050.00	42,721.27	72.69

INSPECTION

Date of Assignment: 18/02/2022

Date Inspected: 21/02/2022 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 12.0 days

Adjuster: Lim Teow Guan**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2022)
Parts:	M1-SUV	PORSCHE MACAN 2.0 PDK CYP E5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH3S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	1,623.00 FL	*1,084.90 FL
2	1		*FRONT BUMPER LH SIDE BRACKET	Necessary	244.00 FL	*244.00 FL
3	1		*FRONT LH FENDER UPPER	Dented	1,121.00 FL	*1,121.00 FL
4	1		*FRONT LH FENDER LOWER	No such part	642.00 FL	*- FL
5	1		*FRONT LH FENDER SPLASH SHIELD	New Damages Occued	231.00 FL	*- FL
6	1		*FRONT LH SPORT RIM	Cut	2,462.00 FL	*2,462.00 FL
7	1		*FRONT LH SHOCK ABSORBER	Dented	1,632.00 FL	*895.00 FL
8	1		*FRONT LH LOWER ARM	Bent	1,342.00 FL	*899.50 FL
9	1		*FRONT LH LOWER ARM BALL JOINT	Dented	113.00 FL	*113.00 FL
10	1		*FRONT LH KNUCKLE ARM	Dented	1,732.00 FL	*1,425.20 FL
11	1		*FRONT LH WHEEL BEARING	Jammed	441.00 FL	*420.00 FL
12	1		*FRONT LH UPPER ARM	Bent	1,022.00 FL	*799.50 FL
13	1		*FRONT LH CONTROL ARM	Bent	903.00 FL	*700.00 FL
14	1		*FRONT LH DOOR	Dented	3,321.00 FL	*2,027.20 FL
15	1		*FRONT LH DOOR LOWER PROTECTOR	Cut	299.00 FL	*217.00 FL
16	1		*FRONT LH WEATHERSTRIP	Necessary	393.00 FL	*393.00 FL
17	1		*FRONT LH DOOR FRAME TRIM TAPE	No such part	178.00 FL	*- FL
18	1		*LH SIDE MIRROR ASSY	New Damages Occued	1,436.00 FL	*- FL
19	1		*LH SIDE ROCKER PANEL GARNISH	Dented	454.00 FL	*320.00 FL
20	2		*LH SIDE ROCKER PANEL GARNISH SPONGE	No such part	121.00 FL	*- FL
21	1		*REAR LH DOOR	Dented	3,482.00 FL	*1,989.40 FL
22	1		*REAR LH DOOR LOWER PROTECTOR	Cut	299.00 FL	*217.00 FL
23	1		*REAR LH DOOR INNER INSULATOR	No such part	16.00 FL	*- FL
24	1		*REAR LH DOOR WEATHERSTRIP SEAL	Necessary	393.00 FL	*393.00 FL
25	1		*REAR LH DOOR STONE GUARD STICKER	Necessary	147.00 FL	*147.00 FL
26	1		*REAR LH DOOR FRAME TRIM TAPE	Not Necessary	178.00 FL	*- FL
27	1		*REAR LH SPORT RIM	New Damages Occued	2,462.00 FL	*- FL
28	1		*REAR LH LOWER ARM	New Damages Occued	1,152.00 FL	*- FL
29	1		*REAR LH SHOCK ABSORBER	New Damages Occued	1,347.00 FL	*- FL
30	1		*REAR LH KNUCKLE ARM	New Damages Occued	1,608.00 FL	*- FL
31	1		*REAR LH TRACK CONTROL ARM	New Damages Occued	932.00 FL	*- FL
32	1		*REAR LH UPPER ARM	New Damages Occued	731.00 FL	*- FL
33	1		*REAR LH FENDER	New Damages Occued	5,531.00 FL	*- FL
34	1		*REAR LH FENDER GLASS WITH RUBBER SEAL	New Damages Occued	405.00 FL	*- FL
35	1		*REAR LH FENDER PROTECTIVE FLIM	New Damages Occued	113.00 FL	*- FL
36	6		*REAR LH FENDER CLINCH PINS	New Damages Occued	86.00 FL	*- FL
37	1		*REAR LH FENDER SPLASH SHIELD	New Damages Occued	443.00 FL	*- FL
38	1		*REAR BUMPER	New Damages Occued	1,633.80 FL	*- FL
39	1		*REAR BUMPER LOWER GARNISH	New Damages Occued	645.00 FL	*- FL
40	1		*REAR BUMPER LH SIDE BRACKET	New Damages Occued	244.00 FL	*- FL
41	1		*HEADLAMP GARNISH LH	Broken	286.00 FL	*286.00 FL
42	1		*BONNET	Repair	2,455.00 FL	*- FL
43	1		*LH FRONT DOOR INNER TRIM BOARD	Serviceable	1,321.00 FL	*- FL
44	1		*LH HEADLAMP ASSY	Broken	6,304.00 FL	*3,245.80 FL
45	1		*SET FRONT LH FENDER SPLASH SHIELD CLIPS	Not Necessary	75.00 FS	*- FS
46	1		*FRONT LH TYRE	Not Necessary	580.00 FS	*- FS

Report was unsubmitted during this print-out.

7/15/22, 9:58 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR LH TYRE	Not Necessary	580.00 FS	*- FS
48	2		*BRAKE FLUID	Not Necessary	120.00 FS	*- FS
49	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Necessary	70.00 FS	*30.00 FS
50	1		*SET REAR LH DOOR INNER TRIM BOARD CLIPS	Not Necessary	70.00 FS	*- FS
51	1		*SET REAR BUMPER CLIPS	Not Necessary	80.00 FS	*- FS
52	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					53,578.80	19,459.50
- List Item Discount on L Items 10.00/10.00% (\$\$)					5,192.38	1,939.95
Total Parts (\$\$)					48,386.42	17,519.55
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	2,000.00	1,200.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,600.00	1,000.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	150.00	0.00
5	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	150.00	60.00
6	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	550.00	300.00
7	REMOVE AND REPLACE FRONT LH DOOR INNER MECHANISM TO NEW DOOR	New	180.00	80.00
8	REMOVE AND REPLACE REAR LH DOOR INNER MECHANISM TO NEW DOOR	New	180.00	0.00
9	REMOVE AND REPLACE REAR INNER TRIMS, CARPET, ROOF LINING, SEATS AND BOARDS TO ASSIST REPAIR	New	550.00	0.00
10	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	550.00	0.00
11	REMOVE AND REINSTALL REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	180.00	0.00
12	RESET AND DIAGNOSE CONTROL UNIT AND FAULT CODES	New	350.00	120.00
Gross Labour Cost (S\$)			6,540.00	2,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >