

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22001594/AGQF3E2

Date: 21/07/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001913759		
Claimant Vehicle No :	SLD8156T	Insured Vehicle No :	SKZ2343E		
Date of Loss:	17/02/2022	Nature of Claim:	TP	Claim No:	270024

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD8156T	Engine No:	L15B4030097
Make & Model:	HONDA VEZEL, 1.5 CVT ABS D/AIRBAG 2WD 5DR (A)	Chassis No:	RU11110093
Reg. Date:	29/06/2016 (Man. Year: 2015)	Odometer:	129884 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,911.04	4,752.00	4,159.04	46.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	2,240.00	440.00	16.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,591.04	6,992.00	4,599.04	39.68
Approved Total (Overridden) (S\$)		5,600.00		
(S\$)	11,591.04	5,600.00	5,991.04	51.69
+ GST 7.00/7.00% (S\$)	811.37	392.00	419.37	51.69
Nett Amount (S\$)	12,402.41	5,992.00	6,410.41	51.69

INSPECTION

Date of Assignment:	21/02/2022	
Date Inspected:	18/02/2022 Inspected At:	J-mart Motor Trading (HQ) BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C Singapore 539186
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jul 2022)

Parts: 144 HONDA VEZEL 1.5 CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLD8156T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH FENDER	Repair	421.10 FL	*- FL
2	1		*FRT LH FENDER QUARTER ARC	Cut	93.10 FL	*93.10 FL
3	1		*FRT LH WING MIRROR	Not Necessary	896.80 FL	*- FL
4	1		*FRT LH RIM	Cut	615.68 FS	*500.00 FS
5	1		*FRT LH DOOR	Distorted	889.20 FL	*889.20 FL
6	1		*FRT LH DOOR STICKER	Necessary	28.70 FL	*28.70 FL
7	1		*FRT LH DOOR OUTER MOULDING	Not Necessary	97.90 FL	*- FL
8	1		*FRT LH DOOR SPEAKER	Not Necessary	209.10 FL	*- FL
9	1		*FRT LH DOOR RUBBER	Not Necessary	153.90 FL	*- FL
10	1		*FRT LH DOOR LOCK	Not Necessary	255.80 FL	*- FL
11	1		*FRT LH DOOR REGULATOR GEAR W/MOTOR	Damaged	516.50 FL	*325.00 FL
12	1		*FRT LH DOOR TRIMBOARD	Cracked	741.70 FL	*645.00 FL
13	2		*FRT LH DOOR HINGES	Not Necessary	117.00 FL	*- FL
14	1		*REAR LH DOOR	Distorted	1,060.60 FL	*1,060.60 FL
15	1		*REAR LH DOOR HINGES	Lower Bent	117.00 FL	*58.50 FL
16	1		*REAR LH DOOR LOCK	Not Necessary	216.60 FL	*- FL
17	1		*REAR LH DOOR REGULATOR GEAR W/MOTOR	Damaged	493.10 FL	*348.00 FL
18	1		*REAR LH DOOR RUBBER	Not Necessary	88.80 FL	*- FL
19	1		*REAR LH DOOR RUBBER STAND	Cut	86.60 FL	*86.60 FL
20	1		*REAR LH DOOR TRIMBOARD	Cracked	540.50 FL	*540.50 FL
21	1		*REAR LH DOOR OUTER MOULDING	Not Necessary	147.80 FL	*- FL
22	1		*REAR LH DOOR SPEAKER	Not Necessary	209.10 FL	*- FL
23	1		*LH ROCKER GARNISH	Deformed	425.90 FL	*425.90 FL
24	15		*LH ROCKER GARNISH CLIPS	Necessary	58.50 FL	*30.00 FL
25	1		*REAR LH FENDER WHEEL ARC GARNISH	Cut	158.90 FL	*158.90 FL
26	1		*REAR LH RIM	Cut	615.68 FS	*500.00 FS
27	1		*LH CENTRE LOCK PILLAR	Repair	825.40 FL	*- FL
28	1		*FRT LH TYRE	Not Necessary	300.00 FS	*- FS
29	1		*REAR LH TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,680.96	5,690.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,769.92	938.00
Total Parts (\$\$)	8,911.04	4,752.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	900.00
2	SPRAY PAINTING	New	1,400.00	1,100.00
3	TRANSFER 2 DOOR PARTS	New	200.00	160.00
4	ALIGNMENT	New	80.00	80.00
Gross Labour Cost (\$\$)			2,680.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >