

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN			Ref:	CS3/LPC22001595/Upa3e2	
	300 BEACH ROAD SINGAPORE 1995		Date:	25/02/2022		
			(	Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBA 7056P	Veh. Inspected		SMD 585D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/22/22/VC05/025470	Excess (\$)		0.00	
	Assign From		Assign Date		18/02/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS PLUS (A)	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	JTDZS3EU70J030203	Colour		BLUE	
	Odometer	67867 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	DUNLOP		7 mm	
	L/H Front Tyre	205/60 R16	DUNLOP		7 mm	
	R/H Rear Tyre	205/60 R16	DUNLOP		7 mm	
	L/H Rear Tyre	205/60 R16	DUNLOP		7 mm	
4. Description of Damages						
	THE VEHICLE SUS PORTION.	STAINED DAMAGES AT THE N/S BODY AND N/S FRONT				
5.	General Information					
	Accident Date	16/02/2022	Inspect Date / T	ime	21/02/2022 ( 11:07 AM )	
	Survey held at	t TAN LIM MOTOR PTE LTD				
		NO.1 DEFU LANE 6 SINGAPORE 539365				
5a.	Sa. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22001595/Upa3e2

Inspected By

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser