

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22001596/APA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220012722
Claimant Vehicle No :	SLP7146R	Insured Vehicle No :	GBE2555C
Date of Loss:	16/02/2022	Nature of Claim:	TP
		Claim No:	8927640385SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7146R		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN038477
Reg. Date:	15/06/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF45HA161698
Colour:	Black	Odometer:	65972 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,943.00	1,744.80	3,198.20	64.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,445.00	3,346.80	4,098.20	55.05
+ GST 7.00/7.00% (S\$)	521.15	234.28	286.87	55.05
Nett Amount (S\$)	7,966.15	3,581.08	4,385.07	55.05
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,763.08		

INSPECTION

Date of Assignment:	22/02/2022		
Date Inspected:	22/02/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,181.00 FS	*1,744.80 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	76.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	249.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	276.00 FS	*- FS
5	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	92.00 FS	*- FS
6	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,131.00 FS	*- FS
7	2		*REAR BUMPER SEAL	Not Necessary	32.00 FS	*- FS
8	2		*REAR BUMPER GUIDE SECTION UPPER -LH/RH	Not Necessary	100.00 FS	*- FS
9	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	52.00 FS	*- FS
10	2		*REAR GUIDE SECTION PIN	Not Necessary	6.00 FS	*- FS
11	2		*REAR PARKING AID SENSOR -INNER /OUTER	Not Necessary	488.00 FS	*- FS
12	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	4,943.00 1,744.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,502.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >