

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001597/AQY3N2**Date:** 29/06/2022**REFERENCE**

Insured/Claimant: VISCOM MACHINE VISION PTE LTD Policy No: 1700094532-03
Date of Loss: 04/02/2022 Nature of Claim: OD Claim No: 4934874919SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFY877J**
Make & Model: AUDI A5 CABRIOLET, 2.0 TFSI QUATTRO (A) Engine No: CYR051531
Reg. Date: 06/12/2017 (Man. Year: 2017) Chassis No: WAUZZZF58JN009633
Colour: Green Odometer: 44229 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$164,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,197.00	7,222.40	7,974.60	52.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,632.00	9,707.00	5,925.00	37.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,829.00	16,929.40	13,899.60	45.09
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	29,229.00	15,329.40	13,899.60	47.55
+ GST 7.00/7.00% (S\$)	2,046.03	1,073.06	972.97	47.55
Nett Amount (S\$)	31,275.03	16,402.46	14,872.57	47.55

INSPECTION

Date of Assignment: 18/02/2022
Date Inspected: 17/02/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 15.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER LOWER COVER	Deformed	2,504.00 FS	*2,003.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	273.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	249.00 FS	*- FS
4	1		*REAR BUMPER STRIP ALUMINIUM TRIM	Not Necessary	1,139.00 FS	*- FS
5	1		*REAR LIGHT REFLECTOR-RH	Not Necessary	46.00 FS	*- FS
6	1		*TAIL LIGHT-RH	Not Necessary	1,269.00 FS	*- FS
7	1		*TAIL LIGHT TRIM-RH	Not Necessary	34.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION-RH	Not Necessary	26.00 FS	*- FS
9	1		*PIN	Not Necessary	3.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION UPPER-RH	Not Necessary	49.00 FS	*- FS
11	1		*REAR FENDER-RH	Dented	5,151.00 FS	*4,120.80 FS
12	1		*REAR SILL TRIM STRIP-RH	Not Necessary	210.00 FS	*- FS
13	1		*REAR SILL PANEL TRIM ATTACHMENT PARTS	Necessary	136.00 FS	*108.80 FS
14	1		*REAR SILL PANEL TRIM ADHESIVE TAPES	Necessary	221.00 FS	*176.80 FS
15	1		*FUEL FILLER FLAP	Not Necessary	343.00 FS	*- FS
16	1		*FUEL FILLER INSERT	Not Necessary	100.00 FS	*- FS
17	1		*REAR WHEEL HOUSING LINER-RH	Not Necessary	260.00 FS	*- FS
18	1		*ALUMINIUM RIM	Not Necessary	1,889.00 FS	*- FS
19	4		*RUBBER VALVE	Not Necessary	15.00 FS	*- FS
20	1		*ARYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
21	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
22	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
23	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
24	1		*SUNDRIES	Necessary	500.00 FS	*32.80 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **15,197.00** **7,222.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO REMOVE AND REINSTALL REAR WIRE HARNESS RELAY FUSE BOXES.AUDIO EQUIPMENT.RHS REAR WINDOW AND LIFTING MECHANISM,RHS TRIMS,LUGGAGE COMPARTMENTS TRIMS	New	1,600.00	1,600.00
3	TO REMOVE AND REINSTALL CONVERTIBALE TOP,COMPLETE WOTH FRAME.HYDRULIC SYSTEM ASSY,STORAGE BOX AND ETC	New	1,800.00	1,800.00
4	TO DISMANTLE AND RENEW REAR BUMPER.TO REMOVE AND REINSTALL RHS SILL PANEL TRIM.TO CUT OUT AND WELD RHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,400.00	3,000.00
5	TO RESPRAY REAR BUMPER,RHS REAR FENDER,RHS SILL PANEL,DOOR ENTRANCE DRAIN CHANNEL.REAR END PANEL AND FUEL CAP	New	5,000.00	2,475.00
6	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			15,632.00	9,707.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >