

ASS. REC. BY: Taught

REF:

CS / ASM 2200 / 599 / 793

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLM 2257C

Policy No. _____

Claims No. S2M03TG9


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$155K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLM P8888P Yr Regn: 2019, Aug

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vellfire c.c. 2493

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 85019 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AGH 30023 7.566

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235 / 50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 12/2/2022

Survey held at Xin Yun

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14/2/23	LS \$3700 confirmed by email (red 11,009.50, 74%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 14/2/23-typist

Rep. Format: TP

Lump Sum / L.S. (\$ \$3700)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

 S + RS SI

) Photos

) Others

TOTAL



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMP8888P 2022 Villfire

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 1,517.30 <i>de</i>
2	1	Rear bumper left bracket	\$ 98.00 <i>re</i>
3	1	Rear bumper tow cover	\$ 68.00 <i>x</i>
4	1	Rear left airvent	\$ 95.00 <i>de</i>
5	1	Corner light	\$ 225.00 <i>x</i>
6	1	Bumper lower side trim	\$ 168.30 <i>de</i>
7	1	Rear fender	\$ 1,883.50 <i>ko</i>
8	1	Rear left door	\$ 2,200.00 <i>ko</i>
9	1	Sport Rim	\$ 2,594.40 <i>art</i>
10	1	Sensor with bracket	\$ 250.00 <i>rw</i>
			\$ 9,099.50



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMP8888P 2022 Vellfire

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips	\$ 80.00 <i>30</i>
2	8	Rear end lower panel top garnish clips	\$ 50.00 <i>x</i>
3	1	Rear side panel sealant	\$ 120.00 <i>x</i>
4	8	Rear fender inner trim board clips	\$ 50.00 <i>x</i>
5	6	Rear door garnish clips	\$ 50.00 <i>x</i>
6	10	Rear lower trim clips	\$ 60.00 <i>x</i>
7	1	Rear no plate with garnish	\$ 80.00 <i>x</i>
sub total special nett			\$ 490.00
Total special nett			\$ 490.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMP8888P 2022 Villfire

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area	\$ 1,800.00 700
2	To putty and spray painting behind portion.	\$ 2,000.00 950
3	To check wiring and focus behind lights	\$ 80.00 X
4	To apply anti rust proofing to front affected area.	\$ 200.00 30
5	To remove and install undercarriage parts.	\$ 150.00 X
6	To balance the wheel.	\$ 80.00 30
7	To conduct wheel alignment.	\$ 120.00 80
8	Ceremic coating for affected area	\$ 150.00 700
9	Remove and install door internal motor, trim to facilitate works	\$ 150.00 60
10	Rear water test	\$ 120.00 X
11	Check rear bumper wiring	\$ 100.00 30
Total repair cost :		5,120.00

Tan Jiah 97495749
'WP' 23/2/22 @ Spr
4/5 Resurvey after repair
Faultless @ 11 hours
05 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: