

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO22001601/Uvf3e2	
	50 RAFFLES PLAC TOWER SINGAPO		Date:	03/03/2022		
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBD 6194P	Veh. Inspected	d	GBL 4280U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2200282/AGC	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		18/02/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV200 VANETTE DX (A)	c.c		1597	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	VM20165907	Colour		WHITE	
	Odometer	12068 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	165/80 R14	TOYO		6 mm	
	L/H Front Tyre	165/80 R14	TOYO		6 mm	
	R/H Rear Tyre	165/80 R14	TOYO		6 mm	
	L/H Rear Tyre	165/80 R14	TOYO		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	E VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
5.	5. General Information					
	Accident Date	19/01/2022	Inspect Date /	Time	21/02/2022 (10:30 AM)	
	Survey held at	A S AUTO SERVICE				
	NO 1 KAKI BUKIT #01-106 SINGAPORE 417883					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,400-\$1,800					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					

Report Ref No. CS3/SMO22001601/Uvf3e2

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser